

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007071/AQY3Q2**Date:** 30/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00128752200

**Claimant Vehicle No :** SNF4885P **Insured Vehicle No :** SKC1342K

Date of Loss: 22/07/2022 Nature of Claim: TP Claim No: SNM22D205114/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNF4885P**

Make & Model: TOYOTA RAZE, 1.0 X CVT (A) Engine No: 1KR3015355

Reg. Date: 30/05/2022 (Man. Year: 2021) Chassis No: A200A0162908

Colour: White Odometer: 3294 km

Engine Capacity: 996 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,951.00	2,620.25	4,330.75	62.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,380.00	1,500.00	52.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,831.00</b>	<b>4,000.25</b>	<b>5,830.75</b>	<b>59.31</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,200.00</b>		
<b>Nett Amount (\$\$)</b>	<b>9,831.00</b>	<b>3,200.00</b>	<b>6,631.00</b>	<b>67.45</b>

**INSPECTION**

Date of Assignment: 25/07/2022

Date Inspected: 27/07/2022 Inspected At: Automobile Hub Enterprise  
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @  
KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2023)
Parts:	144	TOYOTA RAIZE 1.0 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF4885P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	2		*REAR NUMBER PLATE LAMP	Cracked (1 PCS ONLY)	130.00 F	*65.00 FL
4	1		*REAR BUMPER	Deformed	1,245.00 F	*1,245.00 FL
5	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
6	2		*REAR BUMPER SIDE HOLDER	Not Necessary	192.00 F	*- FL
7	1		*REAR BUMPER LOWER GARNISH	Deformed	652.00 F	*652.00 FL
8	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
9	1		*REAR END PANEL	Dented	723.00 F	*723.00 FL
10	1		*REAR END PANEL TOP GARNISH	Deformed	235.00 F	*235.00 FL
11	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
12	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
13	2		*REAR END PANEL AIR VENT	Deformed	104.00 F	*104.00 FL
14	1		*REAR END PANEL ANTENNA SENSOR	Damaged	185.00 F	*185.00 FL
15	1		*TAILGATE	Repair	1,980.00 F	*- FL
16	1		*TAILGATE LOCK	Not Necessary	390.00 F	*- FL
17	1		*TAILGATE WEATHERSTRIPE	Not Necessary	355.00 F	*- FL
18	1		*TAILGATE GLASS MOULDING	Not Necessary	192.00 F	*- FL
19	1		*TAILGATE GLASS SEALANT	Not Necessary	60.00 FS	*- FS
20	1		*RAIZE WORDING	Necessary	58.00 F	*58.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,951.00	3,437.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	816.75
Total Parts (\$\$)	6,951.00	2,620.25

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO APPLY TUFF COAT	New	150.00	60.00
6	TO REMOVE REAR CAMERA	New	100.00	0.00
7	TO REMOVE UPHOLSTERY	New	150.00	40.00
8	TO REMOVE TAILGATE GLASS	New	180.00	0.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,880.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >