

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WC 2187T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILLAMP ASSY RH	NOT NECESSARY	480.00	-
1	TAILLAMP BRACKET RH	NOT NECESSARY	385.00	-
	LESS 10% DISCOUNT		-86.50	ı
			778.50	-
	SPECIAL NETT ITEMS			
1	REAR SAFETY BAR (SN) (50%)	BENT	2,850.00	1,425.00
1	REAR SAFETY BAR BRACKET RH (SN)	TO REPAIR SEE LABOUR	580.00	-
1	REAR LADDAR RH (SN) (50%)	BENT	6,500.00	3,250.00
1	REAR WHEEL ARCH PANEL (SN)	TO REPAIR SEE LABOUR	4,800.00	-
1	REAR WHEEL ARCH BRACKET (SN)	TO REPAIR SEE LABOUR	500.00	-
1	REAR WHEEL ARCH MUDFLAP (SN)	TO REPAIR SEE LABOUR	380.00	-
			15,610.00	4,675.00
	<u>LABOUR</u>			
	LABOUR CHARGES, TO DO CUTTING, WELDING, REPLACE REPAIR, REMOVE REFIX ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR SAFETY BAR BRACKET RH, REAR WHEEL ARCH PANEL, REAR WHEEL ARCH BRACKET AND REAR WHEEL ARCH MUDFLAP.		1,400.00	800.00
	TO CHECK REAR WIRING SYSTEM.	NOT NECESSARY	150.00	-
	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,200.00	500.00
			2,750.00	1,300.00
	GRAND TOTAL		19,138.50	5,975.00



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,750.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/LPC22005495/Rqy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

P

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**