8/25/22, 9:35 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22007076/KQCQ2

Claim No:

M2201822

25/08/2022 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No:

ML000566

Claimant Vehicle No:

SHD695D

Insured Vehicle No: SKJ4231R

Date of Loss: 09/04/2022 Nature of Claim: ΤP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD695D

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C003203 Reg. Date: 21/12/2017 (Man. Year: 2016) Chassis No: VF1ABL15AUC283492

Colour: Metallic White/Red Odometer: 551985 km

Engine Capacity: 1995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Rear Left Side: Sailun 7 mm Sailun 6 mm Front Right Side: Sailun 6 mm Rear Right Side: Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,282.02	483.39	6,798.63	93.36
Miscellaneous Items		0.00	0.00	0.00	
Labour		6,560.00	900.00	5,660.00	86.28
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	13,842.02	1,383.39	12,458.63	90.01
	Approved Total (Overridden) (S\$)		1,100.00		
	(S\$)	13,842.02	1,100.00	12,742.02	92.05
	+ GST 7.00/7.00% (S\$)	968.94	77.00	891.94	92.05
	Nett Amount (S\$)	14,810.96	1,177.00	13,633.96	92.05

INSPECTION

Date of Assignment: 27/07/2022

Trans-Cab Services Pte Ltd (HQ) Date Inspected: 25/07/2022 Inspected At: 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: **KENNETH KONG** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2022)

Parts: RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) Print Code: (Unsubmitted, no print-code for SHD695D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Repair	747.20 FL	*- FL
2	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
3	1		*HEADLAMP LH	Serviceable	743.60 FL	*- FL
4	1		*HEADLAMP PANEL FRT LH	Repair	128.30 FL	*- FL
5	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
6	1		*DOOR HINGE UPPER FRT LH	Repair	274.50 FL	*- FL
7	1		*DOOR HINGE LOWER FRT LH	Repair	300.55 FL	*- FL
8	1		*FENDER PANEL FRT LH	Bent	437.10 FL	*437.10 FL
9	1		*WHEELARCH FRT LH	Serviceable	191.40 FL	*- FL
10	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
11	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
12	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
13	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
14	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
15	1		*DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
16	1		*DOOR MOULDING CLIP	Not Necessary	70.00 FS	*-FS
17	1		*DOOR STICKER TRANSCAB	Necessary	200.00 FS	*60.00 FS
18	1		*DOOR STICKER CLASSIC	Necessary	100.00 FS	*30.00 FS
19	1		*RIM	Serviceable	350.00 FS	*- FS
20	1		*TYRE	Serviceable	300.00 FS	*-FS
21	1		*BUMPER CLIP FRT	Not Necessary	85.00 FS	*- FS
22	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.			
				Sub Total (S\$)	7,950.02	527.10
	- List Item Discount on L Items 10.00/10.00% (S\$)			668.00	43.71	
				Total Parts (S\$)	7,282.02	483.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJ AND REALIGN THE SAME.	New UST	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
	Gross Labour Cost (S\$)		6,560.00	900.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >