

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 6884Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (CONSISTENT)	TO REPAIR SEE LABOUR	2,245.00	-
1	BOOTLID OUTER CHROME MOULDING (CONSISTENT)	NOT NECESSARY	461.50	-
1	BOOTLID 'C180' EMBLEM (CONSISTENT)	NOT NECESSARY	95.00	-
1	BOOTLID C&C LOGO (CONSISTENT)	NOT NECESSARY	50.00	-
1	BOOTLID '7G-TRONIC' EMBLEM (CONSISTENT)	NOT NECESSARY	95.00	-
2	BOOTLID HINGES @\$365.00 (CONSISTENT)	NOT NECESSARY	730.00	-
1	BOOTLID WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	368.00	-
1	BOOTLID INNER LOCK (CONSISTENT)	NOT NECESSARY	455.00	-
1	BOOTLID INNER TRIM LOWER GARNISH (CONSISTENT)	NOT NECESSARY	365.00	-
1	BOOTLID INNER TRIM LOWER (CONSISTENT)	NOT NECESSARY	485.00	-
1	SET BOOTLID INNER TRIM CLIPS (CONSISTENT)	NOT NECESSARY	60.00	-
2	TAILLAMPS @\$950.00 (CONSISTENT)	N/S CRACKED	1,900.00	875.00
2	TAILLAMP BLACK GARNISHS @\$68.00 (CONSISTENT)	NOT NECESSARY	136.00	-
2	TAILLAMP LOWER BRACKETS @\$105.00 (CONSISTENT)	N/S CRACKED	210.00	105.00
1	REAR BUMPER (CONSISTENT)	DISTORTED	1,615.00	1,588.10
1	REAR BUMPER LOWER (CONSISTENT)	NOT FITTED	680.00	-
2	REAR BUMPER SIDE HOLDERS @\$115.00 (CONSISTENT)	N/S CRACKED	230.00	115.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR BUMPER INNER TOP RETAINER (CONSISTENT)	NOT NECESSARY	345.00	-
1	REAR BUMPER BEAM (CONSISTENT)	BENT	750.00	685.00
1	REAR END PANEL (CONSISTENT)	DENTED	1,215.00	980.50
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	485.00	-
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,480.00	-
1	REAR END PANEL TOP BOARD (CONSISTENT)	NOT NECESSARY	820.00	-
1	REAR FENDER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	917.00	-
1	REAR FENDER INNER TRIM N/S (CONSISTENT)	NOT NECESSARY	365.00	-
1	REAR EXHAUST (CONSISTENT)	BENT / TWISTED	1,488.20	1,488.20
2	REAR EXHAUST MOUNTINGS @\$54.00 (CONSISTENT)	TORN	108.00	108.00
1	REAR EXHAUST HEAT SHIELD N/S (CONSISTENT)	BENT	221.20	221.20

Report Ref No. CC4/ASM22007077/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR EXHAUST CHROME (CONSISTENT)	DENTED	220.00	180.00
1	REAR CROSS MEMBER MOUNTING N/S (CONSISTENT)	TORN	165.00	165.00
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	186.00	-
1	REAR WINDSCREEN SEALANT (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (CONSISTENT)	NECESSARY	50.00	50.00
	LESS 10% DISCOUNT		-	-662.10
			19,105.90	5,958.90
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	380.00	200.00
			380.00	200.00
	LABOUR			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO TRANSFER BOOTLID MECHANISM .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		150.00	80.00
	TO DISMANTLE & REPLACED REAR EXHAUST .		100.00	100.00
	TO DISMANTLE & REFIX FUEL TANK .	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		120.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS .INCLUSIVE OF THE REPAIR OF BOOTLID,REAR FLOOR PANEL AND REAR FENDER N/S .		1,500.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,850.00	2,100.00
	GRAND TOTAL		23,335.90	8,258.90
	RECOMMENDED COST OF LUMP SUM REPAIRS			6,600.00

Report Ref No. CC4/ASM22007077/Upa3q2

CHUA KANG SENG

(TO ITS PRE-ACCIDENT CONDITION)

Licensed Appraiser