

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA22007082/UCY3E2

Date: 18/08/2022

### REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP303026  
Claimant Vehicle No : SMT9704J Insured Vehicle No : SLD406A  
Date of Loss: 24/07/2022 Nature of Claim: TP Claim No: MPC03565/WF

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMT9704J  
Make & Model: HONDA CIVIC, 1.6 (A) Engine No: R16B25520097  
Reg. Date: 27/07/2020 (Man. Year: 2020) Chassis No: MRHFC5650LT000039  
Colour: Matt Red Odometer: 19977 km  
Engine Capacity: 1597 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 235/35 R19  
Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm  
Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|--|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 6,896.60        | 1,859.84        | 5,036.76        | 73.03        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 1,780.00        | 1,160.00        | 620.00          | 34.83        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>8,676.60</b> | <b>3,019.84</b> | <b>5,656.76</b> | <b>65.20</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>2,400.00</b> |                 |              |
| <b>(S\$)</b>                             | 8,676.60        | 2,400.00        | 6,276.60        | 72.34        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 607.36          | 168.00          | 439.36          | 72.34        |
| <b>Nett Amount (S\$)</b>                 | <b>9,283.96</b> | <b>2,568.00</b> | <b>6,715.96</b> | <b>72.34</b> |

### INSPECTION

Date of Assignment: 26/07/2022  
Date Inspected: 26/07/2022 Inspected At: Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883  
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 18 Aug 2022)         |
| <b>Parts:</b>        | 143  | HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                     |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMT9704J)  |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition         | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------|-------------------|------------|------------|
| 1   | 1   |          | *FRONT BUMPER                     | Deformed / Warped | 845.20 F   | *579.90 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE RETAINERS      | N/S Cracked       | 61.60 F    | *30.80 FL  |
| 3   | 1   |          | *FRONT BUMPER CENTRE GRILLE       | Not Necessary     | 89.20 F    | *- FL      |
| 4   | 1   |          | *FRONT BUMPER CENTRE TOP BEAM     | Not Necessary     | 165.20 F   | *- FL      |
| 5   | 1   |          | *FRONT BUMPER TOP RUBBER          | Not Necessary     | 68.00 F    | *- FL      |
| 6   | 1   |          | *FRONT BUMPER BEAM                | Bent              | 399.80 F   | *394.80 FL |
| 7   | 1   |          | *FRONT BUMPER FOG LAMP N/S        | Cracked           | 392.50 F   | *315.50 FL |
| 8   | 1   |          | *FRONT BUMPER FOG LAMP COVER N/S  | Twisted           | 199.80 F   | *97.80 FL  |
| 9   | 1   |          | *FRONT GRILLE                     | Not Necessary     | 325.30 F   | *- FL      |
| 10  | 1   |          | *FRONT GRILLE CHROME MOULDING     | Not Necessary     | 288.30 F   | *- FL      |
| 11  | 1   |          | *FRONT GRILLE H LOGO              | Not Necessary     | 38.00 F    | *- FL      |
| 12  | 1   |          | *HEADLAMP N/S                     | Scratched         | 1,825.30 F | *868.50 FL |
| 13  | 1   |          | *HEADLAMP TOP CHROME MOULDING N/S | Not Necessary     | 108.00 F   | *- FL      |
| 14  | 1   |          | *FRONT SUPPORT PANEL              | Repair            | 665.20 F   | *- FL      |
| 15  | 1   |          | *FRONT FENDER N/S                 | Repair            | 485.20 F   | *- FL      |
| 16  | 1   |          | *FRONT SPORT RIM N/S              | Repair            | 850.00 F   | *- FL      |
| 17  | 1   |          | *SET FRONT BUMPER CLIPS           | Necessary         | 30.00 FS   | *30.00 FS  |
| 18  | 1   |          | *SET FRONT GRILLE CLIPS           | Not Necessary     | 30.00 FS   | *- FS      |
| 19  | 1   |          | *SET BONNET INSULATOR CLIPS       | Not Necessary     | 30.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                   | <b>6,896.60</b> | <b>2,317.30</b> |
| <b>- List Item Discount on L Items 0.00/20.00% (S\$)</b> | <b>0.00</b>     | <b>457.46</b>   |
| <b>Total Parts (S\$)</b>                                 | <b>6,896.60</b> | <b>1,859.84</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | TO CHECK WIRING                           | New      | 50.00           | 20.00           |
| 2                               | TO SPRAY RUST PROOFING                    | New      | 60.00           | 0.00            |
| 3                               | TO REFILL AIR CON GAS                     | New      | 120.00          | 0.00            |
| 4                               | TO RESET & REPROGRAMME SYSTEM             | New      | 150.00          | 60.00           |
| 5                               | LABOUR FOR PANEL BEATING & REPLACED PARTS | New      | 600.00          | 400.00          |
| 6                               | TO PUTTY & SPRAY PAINTING                 | New      | 800.00          | 680.00          |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>1,780.00</b> | <b>1,160.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >