

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 9838D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BENT / WARPED	1,475.00	1,475.00
1	BONNET LOCK	SERVICEABLE	185.00	-
1	FRONT BUMPER	DISTORTED	766.20	766.20
2	FRONT BUMPER SIDE RETAINERS @\$65.00	BENT	130.00	130.00
1	FRONT BUMPER BEAM	BENT	399.20	399.20
1	FRONT BUMPER SPONGE	TORN	195.50	195.50
1	FRONT BUMPER CENTRE LOWER GRILLE	TORN	188.20	188.20
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER SIDE GRILLE O/S	TWISTED	112.00	112.00
2	HEADLAMP HID @\$2201.00	HOLDER CRACKED	4,402.00	4,402.00
1	FRONT GRILLE SPORT	CRACKED	650.00	650.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	891.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	TORN	341.20	341.20
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	755.20	-
1	FRONT FENDER INNER SHIELD O/S	TORN	223.50	223.50
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	50.00	50.00
	LESS 25% DISCOUNT		-2,703.50	-2,245.70
			8,110.50	6,737.10
	SPECIAL NETT ITEMS			
1	FRONT LICENCE PLATE (SN)	CRACKED	50.00	40.00
			50.00	40.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO RESET & REPROGRAMME SYSTEM.		180.00	60.00
	TO SPRAY RUST PROOFING.		60.00	30.00
	LABOUR FOR PANEL BEATNG & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL AND FRONT FENDER O/S.		880.00	550.00

Report Ref No. CS/TP22007089/Uvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,000.00	900.00
			2,290.00	1,560.00
	GRAND TOTAL		10,450.50	8,337.10

RECOMMENDED COST OF LUMP SUM REPAIRS		6,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP22007089/Uvy3m4

CHUA KANG SENG

Licensed Appraiser