

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007090/APA3Q2**Date:** 13/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210019927
Claimant Vehicle No :	SMX5278C	Insured Vehicle No :	SGW358P
Date of Loss:	19/07/2022	Nature of Claim:	TP
		Claim No:	5992390188SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX5278C		
Make & Model:	OPEL CROSSLAND, 1.2 (A)	Engine No:	10Z1AE0030964
Reg. Date:	18/01/2021 (Man. Year: 2020)	Chassis No:	W0V7D9EB7L4426613
Colour:	Blue	Odometer:	27337 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,007.20	1,008.00	11,999.20	92.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,960.00	710.00	5,250.00	88.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,967.20	1,718.00	17,249.20	90.94
+ GST 7.00/7.00% (S\$)	1,327.70	120.26	1,207.44	90.94
Nett Amount (S\$)	20,294.90	1,838.26	18,456.64	90.94
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
Nett Liability (S\$)		1,958.26		

INSPECTION

Date of Assignment:	21/07/2022		
Date Inspected:	21/07/2022	Inspected At:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	2.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER CENTRE	Deformed	1,120.00 FL	*1,120.00 FL
2	1		*RR BUMPER RH	Not Necessary	631.00 FL	*- FL
3	1		*RR BUMPER LH	Not Necessary	631.00 FL	*- FL
4	1		*RR BUMPER LOW GARNISH (SILVER)	Not Necessary	408.00 FL	*- FL
5	1		*0RR BUMPER REFLECTOR RH	Not Necessary	124.00 FL	*- FL
6	1		*0RR BUMPER REFLECTOR LH	Not Necessary	124.00 FL	*- FL
7	1		*RR BUMPER TOW COVER	Not Necessary	112.00 FL	*- FL
8	1		*RR BUMPER SIDE RETAINER RH (INNER)	Not Necessary	161.00 FL	*- FL
9	1		*RR BUMPER SIDE RETAINER RH (OUTER)	Not Necessary	140.00 FL	*- FL
10	1		*RR BUMPER CENTER RETAINER	Not Necessary	164.00 FL	*- FL
11	1		*RR BUMPER SIDE RETAINER LH (INNER)	Not Necessary	161.00 FL	*- FL
12	1		*RR BUMPER SIDE RETAINER LH (OUTER)	Not Necessary	140.00 FL	*- FL
13	1		*RR BUMPER LOW BRACKET CENTRE RH	Not Necessary	95.00 FL	*- FL
14	1		*RR BUMPER LOW BRACKET CENTRE LH	Not Necessary	95.00 FL	*- FL
15	1		*RR BUMPER REINFORCEMENT	Not Necessary	703.00 FL	*- FL
16	1		*RR BUMPER REVERSE SENSOR -INNER	Not Necessary	207.00 FL	*- FL
17	1		*RR BUMPER BLIND SPOT SENSOR -OUTER	Not Necessary	262.00 FL	*- FL
18	1		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Not Necessary	12.00 FL	*- FL
19	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	388.00 FL	*- FL
20	1		*RR TAILGATE	Not Necessary	2,155.00 FL	*- FL
21	1		*RR TAILGATE OPEL LOGO	Not Necessary	92.00 FL	*- FL
22	1		*RR TAILGATE CROSSLAND EMBLEM	Not Necessary	85.00 FL	*- FL
23	1		*RR TAILGATE TURBO EMBLEM	Not Necessary	84.00 FL	*- FL
24	1		*RR TAILGATE WEATHERSTRIP	Not Necessary	414.00 FL	*- FL
25	1		*RR TAILGATE LOCK	Not Necessary	287.00 FL	*- FL
26	1		*RR TAILGATE LOCK CATCHER -STRIKER	Not Necessary	135.00 FL	*- FL
27	1		*RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	Not Necessary	151.00 FL	*- FL
28	1		*RR TAILGATE STOPED	Not Necessary	35.00 FL	*- FL
29	1		*RR TAILGATE INNER TRIM BOARD	Not Necessary	592.00 FL	*- FL
30	1		*RR TAILGATE REFLECTOR RH -TAIL LAMP ,T/GATE	Not Necessary	468.00 FL	*- FL
31	1		*RR TAILGATE REFLECTOR LH -TAIL LAMP ,T/GATE	Not Necessary	468.00 FL	*- FL
32	1		*RR TAILGATE GLASS	Not Necessary	945.00 FL	*- FL
33	1		*RR TAILGATE NUMBER PLATE LAMP WITH SWITCH	Not Necessary	359.00 FL	*- FL
34	1		*RR TAILGATE REVERSE CAMERA	Not Necessary	552.00 FL	*- FL
35	1		*RR TAILLAMP RH	Not Necessary	561.00 FL	*- FL
36	1		*RR TAILLAMP LH	Not Necessary	561.00 FL	*- FL
37	1		*RR END PANEL	Not Necessary	409.00 FL	*- FL
38	1		*RR END PANEL AIR DUCT -VENT	Not Necessary	126.00 FL	*- FL
39	1		*RR END PANEL TOP GARNISH	Not Necessary	251.00 FL	*- FL
40	1		*REAR NUMBER PLATE & FRAME	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,448.00	1,120.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,440.80	112.00
Total Parts (\$\$)	13,007.20	1,008.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	3,200.00	650.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (REAR BUMPER ,REAR END PANEL)	New	2,600.00	0.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	80.00	0.00
4	REMOVE AND REPLACE REVERSE SENSOR	New	80.00	60.00
Gross Labour Cost (\$\$)			5,960.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >