

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22007098/KQY3M4**Date:** 07/11/2022**REFERENCE**

Insured/Claimant: RICHARD GIAM KEE CHOO Policy No: MP303026
Date of Loss: 24/07/2022 Nature of Claim: OD Claim No: MPC03565/WF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD406A**
Make & Model: MERCEDES-BENZ CLA180, 1.6 (A) Engine No: 27091030820015
Reg. Date: 31/05/2016 (Man. Year: 2015) Chassis No: WDD1173422N294271
Colour: Metallic Pearl White Odometer: 112905 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$85,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,451.75 | 787.50 | 1,664.25 | 67.88 |
| Miscellaneous Items | 88.00 | 0.00 | 88.00 | 100.00 |
| Labour | 1,750.00 | 420.00 | 1,330.00 | 76.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,289.75 | 1,207.50 | 3,082.25 | 71.85 |
| Approved Total (Overridden) (S\$) | | 950.00 | | |
| - Excess (S\$) | 0.00 | 500.00 | -500.00 | |
| (S\$) | 4,289.75 | 450.00 | 3,839.75 | 89.51 |
| + GST 7.00/7.00% (S\$) | 300.28 | 31.50 | 268.78 | 89.51 |
| Nett Amount (S\$) | 4,590.03 | 481.50 | 4,108.53 | 89.51 |

INSPECTION

Date of Assignment: 26/07/2022 Present Location: S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 29/07/2022 Inspected At: S & H Motor Pte Ltd (Sin Ming)
Estimated Period of Repair: 2.0 days 160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 07 Nov 2022) |
| Parts: | 143 | MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLD406A) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|--------------------------------|--|-------------------|
| 1 | 1 | | *Rear bumper (WCP) | Buckled / Dented | 750.00 F | *750.00 F |
| 2 | 1 | | *RH Rear bumper retainer (WCP) | Serviceable | 35.00 F | *- F |
| 3 | 1 | | *RH rear fender (Dented) (WCP) | Not Consistent With The Impact | 1,550.00 F | *- F |
| | | | | | | F=Franchise part. |
| | | | | | Sub Total (S\$) | 2,335.00 750.00 |
| | | | | | + Margin on L,N Items 5.00/5.00% (S\$) | 116.75 37.50 |
| | | | | | Total Parts (S\$) | 2,451.75 787.50 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|---|--------------|-------------|
| Miscellaneous Items | | | | |
| 1 | 1 | Rear windscreen inner seal (Not Necessary) | 28.00 | 0.00 |
| 2 | 1 | Rear windscreen sealant (Not Necessary) | 60.00 | 0.00 |
| Sub Total (\$\$) | | | 88.00 | 0.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | To remove and reinstall rear windscreen and conduct water leak test. | New | 120.00 | 0.00 |
| 2 | To remove rear damaged parts, to jack out RH rear fender, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, RH rear door to replace damaged parts and adjust rear body and tailgate alignment | New | 750.00 | 200.00 |
| 3 | To spray paint affected rear and inner damaged portion inclusive of preparatory works and material | New | 650.00 | 220.00 |
| 4 | To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality | New | 80.00 | 0.00 |
| 5 | To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes | New | 150.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,750.00 | 420.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >