10/10/22, 9:47 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22007099/UQY3E2

10/10/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMB1SNW00004102200

Claimant Vehicle

Insured

PC8056G

No:

SKA1166M

Vehicle No:

Odometer:

Date of Loss:

24/07/2022

Nature of Claim: TP

Claim

SNM22D205181/C02/LEWLC

50449 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKA1166M Reg No:

10FKBA2565914 CITROEN C5 AIRCROSS, 1.6 L SHINE (A) Make & Model: Engine No: Reg. Date: 27/09/2019 (Man. Year: 2019) Chassis No: VR7A45GFRKL072409

Colour: White

Engine Capacity: 1598 cc N/A

Market Value/New Car Price: Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18 Front Left Side: Rear Left Side: Michelin 8 mm Michelin 8 mm Front Right Side: Rear Right Side: Michelin 8 mm Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,715.00	720.00	1,995.00	73.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	525.41	428.81	96.60	18.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,240.41	1,148.81	2,091.60	64.55
+ GST 7.00/7.00% (S\$)	226.83	80.42	146.41	64.55
Nett Amount (S\$)	3,467.24	1,229.23	2,238.01	64.55

INSPECTION

Date Inspected:

Date of Assignment: 26/07/2022

> Jin Auto Services Pte Ltd (Defu) 29/07/2022 Inspected At:

Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Oct 2022)

Parts: CITROEN C5 AIRCROSS 1.6 L SHINE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA1166M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CPL	Repair	1,100.00 F	*-F
2	1		*RR CTR IMPACT ABSORB	Not Necessary	180.00 F	*- F
3	1		*REAR BUMPER SUPPORT	Not Necessary	380.00 F	*- F
4	1		*L/R INN PARKING SENS	Not Necessary	120.00 F	*- F
5	1		*R/R INN PARKING SENS	Not Necessary	120.00 F	*- F
6	1		*RR BUMPER LOWER	Torn	620.00 F	*620.00 F
7	1		*RR BUMPER TOW CVR	Serviceable	95.00 F	*- F
8	1		*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
F=Fra	anchise	part. S=SpcNe	tt.			
				Total Parts (S\$)	2,715.00	720.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TOTAL 38.0 WU X 42.00 SGD/H	New	159.60	63.00
2	LABOUR COST 60.0 WU X 42.00 SGD/H	New	252.00	252.00
3	MATERIAL COST	New	113.81	113.81
		Gross Labour Cost (S\$)	525.41	428.81
	Report was u	unsubmitted during this print-out.		

< END OF ESTIMATES >