



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 9752U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FR BUMPER (WCP)	CRACKED	240.00	240.00
1	FR BUMPER CLIPS (WCP)	NECESSARY	50.00	50.00
1	RETAINER L & R (WCP)	O/S CRACKED	60.00	30.00
1	REINFORCEMENT (WCP)	TO REPAIR SEE LABOUR	135.00	-
1	RADIATOR GRILLE (WCP)	CRACKED	85.00	85.00
1	FIAT EMBLEM (WCP)	NECESSARY	85.00	85.00
1	LH HEADLAMP (WCP)	MTG BROKEN	200.00	200.00
1	RH HEADLAMP (WCP)	MTG BROKEN	200.00	200.00
1	RHF FENDER (WCP)	BENT	200.00	200.00
1	LHF FENDER (BENT) (WCP)	NOT CONSISTENT WITH THE IMPACT	200.00	-
1	LHF FENDER SHIELD (CRACKED) (WCP)	NOT CONSISTENT WITH THE IMPACT	200.00	-
1	RHF FENDER SHIELD (WCP)	CRACKED	200.00	200.00
1	RH DOOR HINGES TOP (WCP)	TO REPAIR SEE LABOUR	70.00	-
1	RH DOOR HINGE BTM (WCP)	TO REPAIR SEE LABOUR	70.00	-
1	RHF DOOR A- FRAME (WCP)	TO REPAIR SEE LABOUR	655.00	-
1	RHF DOOR (WCP)	BENT	950.00	950.00
1	RHF DOOR PROTECTOR (WCP)	MISSING	70.00	70.00
1	RHS SLIDING DOOR (WCP)	BENT	1,500.00	1,500.00
1	RH WING MIRROR (WCP)	CRACKED	240.00	240.00
1	RHF RIM (WCP)	BENT	315.00	315.00
1	ENGINE UNDERCOVER (WCP)	SERVICEABLE	360.00	-
1	ENGINE UNDERCOVER CLIPS (WCP)	NOT NECESSARY	50.00	-
1	BONNET HINGE RH (WCP)	TO REPAIR SEE LABOUR	70.00	-
1	RHF & RHS SLIDING DOOR OUTER HANDLE (WCP)	DENTED	345.00	345.00
	COST PLUS 10%		-	471.00

Report Ref No. CS/AWA22007104/Kcy3m4



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	COST PLUS 15%		982.50	-
			7,532.50	5,181.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	WRAPPER STICKERS (SN)	NECESSARY	1,820.00	1,000.00
			1,820.00	1,000.00
	<b><u>LABOUR</u></b>			
	REMOVE, REPLACE, REPAIR & REFIT. INCLUSIVE OF THE REPAIR OF REINFORCEMENT, RH DOOR HINGES TOP, RH DOOR HINGE BTM, RH DOOR A- FRAME AND BONNET HINGE RH.		1,000.00	750.00
	RESPRAY PAINTING.		1,200.00	1,000.00
	FRT WHEEL ALIGNMENT.		60.00	60.00
	CHECK LIGHTS & WIRING.		100.00	30.00
	RECHARGE AC GAS (NPA).	NOT NECESSARY	-	-
	REAR WHEEL ALIGNMENT.		150.00	60.00
	REPLACE STICKER WRAP (NPA).	NOT INSURED	-	-
	MODULATOR RESET (NPA).	NOT NECESSARY	-	-
			2,510.00	1,900.00
	<b>GRAND TOTAL</b>		<b>11,862.50</b>	<b>8,081.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,400.00</b>
	<b>LESS EXCESS</b>			<b>-2,500.00</b>
	<b>NETT LIABILITY</b>			<b>3,900.00</b>

Report Ref No. CS/AWA22007104/Kcy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.