

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I			Ref:	CS3/ASM22007105/Ecy3e2	
	8 SHENTON WAY TOWERSINGAPOR		Date:	16/08/2022		
	ATTN: OH VALE			Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 384B	Veh. Inspected		SMA 2604K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M047GZ	Excess (\$)		0.00	
	Assign From	OH VALE	Assign Date		26/07/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 520I	c.c		1995	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	WBANT12050CX30238	Colour		BLUE	
	Odometer	162797 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/50 R17	MICHELIN		4 mm	
	L/H Front Tyre	215/50 R17	MICHELIN		4 mm	
	R/H Rear Tyre	215/50 R17	MICHELIN		4 mm	
	L/H Rear Tyre	215/50 R17	MICHELIN		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information						
	Accident Date	24/07/2022	Inspect Date /	Time	27/07/2022 ( 01:14 PM )	
	Survey held at	T L S AUTO ENGINEERING PTE LTD				
		BLK 1010 BUKIT MERAH LANE 3 #01-13 SINGAPORE 159724				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					

Report Ref No. CS3/ASM22007105/Ecy3e2

Inspected By

**CHEN TSUE YEE** 

**Automotive Assessor** 

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**