

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122007110/ACY3E2**Date:** 10/10/2022**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SDU1733D**Insured Vehicle No :** SJD5503T

Date of Loss: 22/07/2022

Nature of Claim: TP

Claim No: CDMPG22001454

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SDU1733D**

Make & Model: CHEVROLET ORLANDO, 1.4 Turbo (A)

Engine No: B14NET153650315

Reg. Date: 31/03/2016 (Man. Year: 2015)

Chassis No: KL1YA7589GK333166

Colour: Brown

Odometer: 122794 km

Engine Capacity: 1362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,327.00	9,226.40	4,100.60	30.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,100.00	1,480.00	41.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,907.00	11,326.40	5,580.60	33.01
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	16,907.00	9,000.00	7,907.00	46.77

INSPECTION

Date of Assignment: 26/07/2022

Date Inspected: 25/07/2022 Inspected At:

ADVANCE AUTO GARAGE (23 KAKI BUKIT) (HQ)

25 KAKI BUKIT AVE 4 #04-01 VICOM KAKI BUKIT

Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2022)
Parts:	M1-MPV	CHEVROLET ORLANDO 1.4 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDU1733D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Distorted	1,330.00 F	*1,330.00 FL
2	1		*REAR BUMPER LOWER	Distorted	493.00 F	*493.00 FL
3	1		*REAR BUMPER SILL PLATE (SILVER)	Missing	223.00 F	*223.00 FL
4	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	236.00 F	*- FL
6	1		*REAR BUMPER STEP PLATE	Missing	166.00 F	*166.00 FL
7	1		*REAR BUMPER REFLECTOR	O/S Cracked	280.00 F	*140.00 FL
8	1		*REAR BUMPER BRAKE LAMP	Cracked	307.00 F	*307.00 FL
9	1		*REAR BUMPER CENTRE GUIDE	Cracked	148.00 F	*148.00 FL
10	2		*REAR BUMPER SIDE GUIDE	Not Necessary	224.00 F	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Dented	863.00 F	*863.00 FL
12	1		*REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	860.00 F	*430.00 FL
13	4		*REVERSE SENSOR SEAL	Necessary	60.00 F	*60.00 FL
14	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	291.00 F	*- FL
15	1		*REAR END PANEL	Dented	776.00 F	*776.00 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	186.00 F	*186.00 FL
17	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
18	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
19	1		*TAILLAMP	O/S Cracked	936.00 F	*468.00 FL
20	1		*TAILGATE	Dented	1,528.00 F	*1,528.00 FL
21	1		*TAILGATE LOCK	Damaged	331.00 F	*331.00 FL
22	1		*TAILGATE WEATHERSTRIPE	Cut	272.00 F	*272.00 FL
23	1		*TAILGATE REFLECTOR	O/S Cut	656.00 F	*328.00 FL
24	1		*TAILGATE INNER TRIM BOARD	Cracked	311.00 F	*311.00 FL
25	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*CHERVOLET WORDING	Necessary	133.00 F	*133.00 FL
27	1		*ORLANDO WORDING	Necessary	108.00 F	*108.00 FL
28	1		*LS WORDING	Necessary	45.00 F	*45.00 FL
29	1		*TURBO EMBLEM	Necessary	151.00 F	*151.00 FL
30	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
31	1		*REAR RH FENDER INNER TRIM BOARD	Cracked	781.00 F	*781.00 FL
32	1		*REAR RH FENDER INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
33	1		*SPARE TYRE PANEL TOOL BOX	Deformed	418.00 F	*418.00 FL
34	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	284.00 F	*- FL
35	1		*REAR CAMERA	Not Necessary	680.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,327.00	10,226.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	999.60
Total Parts (\$\$)	13,327.00	9,226.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO SPRAY TUFF COAT	New	150.00	60.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE VIDEO RECORDER	New	100.00	50.00
Gross Labour Cost (\$\$)			3,580.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >