

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122007114/KQY3Q2**Date:** 29/09/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMJ6787S**Insured Vehicle No :** GBJ6246S

Date of Loss: 23/07/2022

Nature of Claim: TP

Claim No: CDMCG22001460

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMJ6787S**

Make &amp; Model: MERCEDES-BENZ E200K, 1.8 (A)

Engine No: 27195630894337

Reg. Date: 12/11/2007 (Man. Year: 2007)

Chassis No: WDB2110412B149241

Colour: Metallic Black

Odometer: 342003 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size:

225/50 R17

Front Left Side: Goodyear 4 mm

Rear Left Side:

Goodyear 5 mm

Front Right Side: Goodyear 4 mm

Rear Right Side:

Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,061.20	7,818.20	243.00	3.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,900.00	340.00	15.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,301.20</b>	<b>9,718.20</b>	<b>583.00</b>	<b>5.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,750.00</b>		
<b>(S\$)</b>	10,301.20	7,750.00	2,551.20	24.77
<b>+ GST 7.00/7.00% (S\$)</b>	721.08	542.50	178.58	24.77
<b>Nett Amount (S\$)</b>	<b>11,022.28</b>	<b>8,292.50</b>	<b>2,729.78</b>	<b>24.77</b>

INSPECTION

Date of Assignment: 26/07/2022

Date Inspected: 27/07/2022 Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #04-01, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 7.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2022)
<b>Parts:</b>	143	MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ6787S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,495.00 FN	*1,495.00 FN
2	1		*REAR BUMPER REINFORCEMENT	Bent	775.00 FN	*775.00 FN
3	1		*REAR BUMPER CENTRE CHROME MOULDING	Necessary	220.00 FN	*220.00 FN
4	1		*REAR BUMPER CHROME MOULDING LH	Necessary	155.00 FN	*155.00 FN
5	1		*REAR BUMPER CHROME MOULDING RH	Necessary	155.00 FN	*155.00 FN
6	1		*REAR BUMPER CENTRE INNER PART	Serviceable	270.00 FN	*- FN
7	1		*REAR BUMPER LOWER BRACKET LH	Missing	22.00 FN	*22.00 FN
8	1		*REAR BUMPER LOWER BRACKET RH	Missing	22.00 FN	*22.00 FN
9	1		*REAR TAIL LAMP LH	Broken	520.00 FN	*520.00 FN
10	1		*REAR BOOT LID	Buckled	2,660.00 FN	*2,660.00 FN
11	1		*REAR BOOT LID LOCK	Dented	360.00 FN	*360.00 FN
12	1		*REAR BOOT LID LOGO EMBLEM	Necessary	55.00 FN	*55.00 FN
13	1		*REAR BOOT LID E200 EMBLEM	Necessary	95.00 FN	*95.00 FN
14	1		*REAR BOOT LID KOMPRESSOR EMBLEM	Necessary	125.00 FN	*125.00 FN
15	1		*REAR BOOT LID CHROME MOULDING	Warped	153.00 FN	*153.00 FN
16	1		*REAR LUGGAGE SIDE COVERING LH	Cracked	36.00 FN	*36.00 FN
17	5		*REAR LUGGAGE SIDE COVERING CLIPS	Necessary	45.00 FN	*45.00 FN
18	1		*REAR END PANEL	Bent	880.00 FN	*880.00 FN
19	1		*REAR END PANEL INNER TRIM GARNISH	Buckled	185.00 FN	*185.00 FN
20	1		*SET REAR REVERSING SENSOR +INSTALLATION	Dented / Shorted (4 PCS)	350.00 FS	*350.00 FS
21	1		*THIRD BRAKE LAMP	Cracked	340.00 FN	*340.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>8,918.00</b>	<b>8,648.00</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	856.80	829.80
<b>Total Parts (S\$)</b>	<b>8,061.20</b>	<b>7,818.20</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK /CLEAR FAULT CODES AFTER REPAIR	New	120.00	0.00
2	TUFF COAT	New	80.00	60.00
3	TO TRANSFER REVERSING CAMERA	New	40.00	40.00
4	TO STRAIGHTEN REAR BODY INCLUDING CUTTING +WELDING TO KNOCK DENTS ON TAIL LAMP PANEL LH AND RENEW OF PARTS	New	900.00	800.00
5	TO SPRAY PAIN (INCLUDING REAR NUMBER PLATE GARNISH)	New	1,000.00	900.00
6	TO REPAIR HEADREST (FRONT SEATS)	New	100.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,240.00</b>	<b>1,900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >