

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007116/DCY3Q2**Date:** 01/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00003872200

**Claimant Vehicle No :** SMX6923S **Insured Vehicle No :** SMD4010U

Date of Loss: 25/07/2022 Nature of Claim: TP Claim No: SNM22D205180C02/LYNN

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMX6923S**

Make & Model: HONDA FREED HYBRID, 1.5 G (A) Engine No: LEB5625729

Reg. Date: 10/04/2019 (Man. Year: 2018) Chassis No: GB71087644

Colour: White Odometer: 218005 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16

Front Left Side: Tourador 5 mm Rear Left Side: Tourador 5 mm

Front Right Side: Tourador 5 mm Rear Right Side: Tourador 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	27,730.85	7,957.64	19,773.21	71.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,750.00	1,970.00	5,780.00	74.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>35,480.85</b>	<b>9,927.64</b>	<b>25,553.21</b>	<b>72.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,500.00</b>		
<b>(S\$)</b>	35,480.85	7,500.00	27,980.85	78.86
<b>+ GST 7.00/7.00% (S\$)</b>	2,483.66	525.00	1,958.66	78.86
<b>Nett Amount (S\$)</b>	<b>37,964.51</b>	<b>8,025.00</b>	<b>29,939.51</b>	<b>78.86</b>

**INSPECTION**

Date of Assignment: 30/11/2022

Date Inspected: 27/07/2022 Inspected At: JWG International Pte Ltd (HQ)  
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK  
AutoPoint  
Singapore 568047

Estimated Period of Repair: 6.0 days

**Adjuster:** BRYAN TANI**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Dec 2022)**Parts:** M1-MPV HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMX6923S)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,960.40 FL	*1,115.90 FL
2	1		*TAILGATE CENTER CHROME	Mtg Cracked	420.40 FL	*315.80 FL
3	1		*TAILGATE HONDA LOGO	Necessary	62.50 FL	*62.50 FL
4	2		*TAILGATE LAMP L+R	Mtg Cracked	1,330.90 FL	*724.00 FL
5	1		*TAILGATE WINDSCREEN MOULDING	Necessary	345.89 FL	*82.50 FL
6	2		*TAILGATE WINDSCREEN MOULDING LH/RH	No such part	259.30 FL	*- FL
7	1		*TAILGATE LOCK	Damaged	367.10 FL	*187.50 FL
8	1		*TAILGATE SWITCH	Not Necessary	375.50 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Mtg Cracked	788.56 FL	*388.40 FL
10	1		*TAILGATE WEATHERSTRIP	Deformed	388.98 FL	*241.70 FL
11	1		*REAR WINDSCREEN GLASS	Shattered	1,829.00 FL	*1,252.30 FL
12	2		*TAIL LAMP LH/RH	Mtg Cracked	2,558.00 FL	*1,258.20 FL
13	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	390.00 FL	*- FL
14	1		*REAR BUMPER	Dented / Cracked	1,065.99 FL	*829.40 FL
15	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	369.80 FL	*- FL
16	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	385.60 FL	*- FL
17	1		*REAR BUMPER TOW HOOK COVER	Serviceable	74.00 FL	*- FL
18	1		*REAR END PANEL	Dented	1,453.70 FL	*509.40 FL
19	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	335.44 FL	*199.70 FL
20	1		*KEYLESS ENTRY SENSOR	Not Necessary	274.84 FL	*- FL
21	1		*KEYLESS BUZZER	Not Necessary	220.50 FL	*- FL
22	1		*SPARE WHEEL PANEL	Not Necessary	1,980.28 FL	*- FL
23	1		*SPARE WHEEL PANEL TOP BOARD	Serviceable	329.40 FL	*- FL
24	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	1,378.40 FL	*- FL
25	1		*SPARE WHEEL PANEL INSULATOR	Not Necessary	399.28 FL	*- FL
26	2		*REAR FENDER LH/RH	Not Necessary	4,188.00 FL	*- FL
27	2		*REAR FENDER INNER TRIM BOARD LH/RH	Mtg Broken	1,568.00 FL	*1,311.00 FL
28	2		*REAR FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	784.00 FL	*- FL
29	1		*REAR EXHAUST MUFFLER	Not Necessary	1,294.30 FL	*- FL
30	1		*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	98.00 FL	*- FL
31	1		*REAR NUMBER PLATE	Bent	100.00 FS	*45.00 FS
32	1		*REAR BUMPER TOP CHROME	Bent	300.00 FS	*80.00 FS
33	1		*SET REAR REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
36	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
38	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
39	1		*TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*15.00 FS
40	1		*TAILGATE LAMP CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*TAILGATE CENTER CHROME STICKER	Necessary	200.00 FS	*50.00 FS
42	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*TAILGATE STICKER	Not Necessary	800.00 FS	*- FS
45	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
48	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
49	1		*REAR END PANEL TOP GARNISH CHROME	Bent	300.00 FS	*80.00 FS
50	1		*TAILGATE TRIMBOARD SOUND PROOFING STICKER	Necessary	1,000.00 FS	*150.00 FS
51	1		*TAILGATE ELECTRONIC DAMPING (CLOSE/OPEN)	Damaged	2,000.00 FS	*400.00 FS
52	1		*REAR WINDSCREEN GLASS TOURER STICKER	Necessary	150.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>33,186.06</b>	<b>9,653.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	5,455.21	1,695.66
<b>Total Parts (\$)</b>	<b>27,730.85</b>	<b>7,957.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,600.00	800.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,600.00	800.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR SLIDING DOOR TO FACILITATE REPAIRS	New	400.00	0.00
6	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
7	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
8	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	400.00	0.00
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
10	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	New	200.00	40.00
11	TO CHECK & REFIX ALL ELECTRICAL WIRING	New	200.00	30.00
			<b>Gross Labour Cost (\$\$)</b>	<b>7,750.00</b>
				<b>1,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >