



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 2595R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	TO REPAIR SEE LABOUR	1,183.00	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	339.00	-
1	BONNET BOTTOM LOCK ASSY	TO REPAIR SEE LABOUR	158.00	-
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	835.00	-
1	SUPPORT PANEL TOP GARNISH	SERVICEABLE	298.00	-
1	HEADLAMP SUPPORT O/S	SERVICEABLE	167.00	-
1	HEADLAMP O/S	CUT	1,196.00	980.00
1	HEADLAMP LOWER BRACKET O/S	SERVICEABLE	78.00	-
1	FRONT BUMPER	BUCKLED /DENTED	986.00	616.25
1	FRONT GRILLE OUTER MOULDING	DENTED	375.00	354.00
1	FRONT BUMPER 'TOYOTA' LOGO	NECESSARY	65.00	65.00
2	FRONT BUMPER SIDE RETAINER @\$73.00	O/S DISTORTED	146.00	73.00
2	FRONT BUMPER BRACKET @\$54.00	TO REPAIR SEE LABOUR	108.00	-
1	FRONT BUMPER UPPER GRILLE	SERVICEABLE	457.00	-
1	FRONT BUMPER SPONGE	SERVICEABLE	278.00	-
1	FRONT BUMPER LOWER GRILLE	CRACKED / DISTORTED	394.00	118.20
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	589.00	-
1	FRONT BUMPER TOW COVER	SERVICEABLE	78.00	-
1	FRONT BUMPER SIGNAL LAMP O/S	SCRATCHED	195.00	195.00
1	FRONT BUMPER FOG LAMP O/S	MTG CRACKED	294.00	249.50
1	FRONT BUMPER FOG LAMP GARNISH O/S	CUT	95.00	95.00
1	FRONT BUMPER LICENCE PLATE BASE	DENTED	76.00	76.00
1	FRONT BUMPER LOWER COWLING	SERVICEABLE	145.00	-
	LESS 25% DISCOUNT		-2,133.75	-705.49
			6,401.25	2,116.46

Report Ref No. CS/AGI22007117/Kny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
12	BONNET INSULATOR CLIPS @\$5.50 (SN)	NOT NECESSARY	66.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
12	FRONT BUMPER CLIPS @\$5.50 (SN)	NECESSARY	66.00	66.00
1	FRONT LICENCE PLATE & FRAME (SN)	DENTED	55.00	45.00
8	SUPPORT PANEL TOP GARNISH CLIPS @\$5.50 (SN)	NOT NECESSARY	44.00	-
10	FRONT BUMPER LOWER COWLING CLIPS @\$5.50 (SN)	NOT NECESSARY	55.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			416.00	111.00
	<u>LABOUR</u>			
	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTIONS .TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF BONNET,BONNET LOCK,BONNET BOTTOM LOCK ASSY,SUPPORT PANEL,FRONT BUMPER BRACKET AND FRONT BUMPER REINFORCEMENT.		1,200.00	300.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS.		50.00	20.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL .		1,000.00	350.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.	NOT NECESSARY	100.00	-
			2,350.00	670.00
	GRAND TOTAL		9,167.25	2,897.46
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00

Report Ref No. CS/AGI22007117/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.