

ASS. REC. BY:

REF:

AG2/220071171Kny3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKV 2585R

Yr Regn:

09, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Prius

c.c

1897

Colour

N. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

215297

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDDK03B30010P0346

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/80R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirius

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

24/7/22

D.O.I.

27/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rm O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 EN NOTICED

29/7 L1 Rm @ 2300. Cncl (Red. \$ 6867.25, 75%)

Date/Time, File Pass to?



: Prell. Report

1) 31/8/22



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Firms


) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

2300

Thiam Heng Huat Pte Ltd176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com*Not Withheld*
1/12/23 8 2300h
Resurvey After Repair
*3 days*Make/Model: TOYOTA PRIUS C HYBRID
Engine/Chassis No.: JTDKD3B3001090346
Date of accident:
Damaged area: O/S FrontDate: 27/07/2022
Claim Type: TP
VRN: SKV2595R

List items					
S/N	Parts description		QTY	UNIT PRICE	AMOUNT
1	Bonnet	<i>R</i>	1	\$ 1,183.00	\$ 1,183.00
2	Bonnet lock	<i>R</i>	1	\$ 339.00	\$ 339.00
3	Bonnet bottom lock assy	<i>R</i>	1	\$ 158.00	\$ 158.00
4	Support panel	<i>R</i>	1	\$ 835.00	\$ 835.00
5	Support panel top garnish	<i>R</i>	1	\$ 298.00	\$ 298.00
6	Headlamp support o/s	<i>R</i>	1	\$ 167.00	\$ 167.00
7	Headlamp o/s <i>980</i>	<i>R</i>	1	\$ 1,196.00	\$ 1,196.00
8	Headlamp lower bracket o/s	<i>R</i>	1	\$ 78.00	\$ 78.00
9	Front bumper <i>616-25</i>	<i>Bu/ld</i>	1	\$ 986.00	\$ 986.00
10	Front grille outer moulding <i>354</i>	<i>nd</i>	1	\$ 375.00	\$ 375.00
11	Front bumper "TOYOTA" logo	<i>nd</i>	1	\$ 65.00	\$ 65.00
12	Front bumper side retainer <i>o/s o/s</i>		2	\$ 73.00	\$ 146.00
13	Front bumper bracket	<i>R</i>	2	\$ 54.00	\$ 108.00
14	Front bumper upper grille	<i>R</i>	1	\$ 457.00	\$ 457.00
15	Front bumper sponge	<i>R</i>	1	\$ 278.00	\$ 278.00
16	Front bumper lower grille <i>118-20</i>	<i>cm/d/s</i>	1	\$ 394.00	\$ 394.00
17	Front bumper reinforcement	<i>R</i>	1	\$ 589.00	\$ 589.00
18	Front bumper tow cover	<i>R</i>	1	\$ 78.00	\$ 78.00
19	Front bumper signal lamp o/s	<i>R</i>	1	\$ 195.00	\$ 195.00
20	Front bumper fog lamp o/s <i>249-50</i>	<i>mg/cm</i>	1	\$ 294.00	\$ 294.00
21	Front bumper fog lamp garnish o/s	<i>R</i>	1	\$ 95.00	\$ 95.00
22	Front bumper licence plate base	<i>nd</i>	1	\$ 76.00	\$ 76.00
23	Front bumper lower cowl	<i>R</i>	1	\$ 145.00	\$ 145.00
				Subtotal	\$ 8,535.00
				List discount	25.00%
				Total	\$ 6,401.25

Special nett items

No.	Parts description	QTY	UNIT PRICE	AMOUNT
-----	-------------------	-----	------------	--------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

1	Bonnet insulator clips	nn	12	\$ 5.50	\$ 66.00	X
2	Radiator coolant	nn	1	\$ 80.00	\$ 80.00	X
3	Front bumper clips	nn	12	\$ 5.50	\$ 66.00	✓
4	Front licence plate & frame	nn	1	\$ 55.00	\$ 55.00	451n
5	Support panel top garnish clips	nn	8	\$ 5.50	\$ 44.00	X
6	Front bumper lower cowlings clips	nn	10	\$ 5.50	\$ 55.00	X
7	Sundries	nn	1	\$ 50.00	\$ 50.00	X
				Total	\$ 416.00	

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ nn 100.00
Total labour			\$ 2,350.00

Estimate Grand Total	\$ 9,167.25
-----------------------------	--------------------

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplemental item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: