

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	_	Ref:	CS3/LPC22007119/Tvy3m4	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	01/08/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBE 9357L	Veh. Inspected		SDD 8328J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/026034	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		26/07/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA STREAM	c.c		1799	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	RN61084363	Colour		SILVER	
	Odometer	358158 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	KAPSEN		6 mm	
	L/H Front Tyre	215/55 R17	KAPSEN		6 mm	
	R/H Rear Tyre	215/55 R17	KAPSEN		6 mm	
	L/H Rear Tyre	215/55 R17	KAPSEN		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	14/07/2022	Inspect Date / T	Time	27/07/2022 (10:50 AM)	
	Survey held at	S9 BUILDING 55 SERANGOON NORTH AVE 4, #02-10				
	Repairer	1 STOP GARAGE PTE. LTD.				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22007119/Tvy3m4

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor