

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI22007121/TCY3E2
Date: 04/11/2022

REFERENCE

| | | |
|---|-------------------------------|----------------------------------|
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: DMCVSNW00111172100 | |
| Claimant Vehicle No : GBK3483M | Insured Vehicle No : GBH4756K | |
| Date of Loss: 24/07/2022 | Nature of Claim: TP | Claim No: SNM22D205178/C02/IRENE |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No: | GBK3483M | Engine No: | 1KDB030413 |
| Make & Model: | TOYOTA HIACE, 3.0 D TURBO 5DR MT (M) | Chassis No: | JTFHT02P400250384 |
| Reg. Date: | 01/06/2020 (Man. Year: 2019) | Odometer: | 76702 km |
| Colour: | Black | | |
| Engine Capacity: | 2982 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 195 R15 | Rear Tyre Size: | 195 R15 |
| Front Left Side: | Royal Black 6 mm | Rear Left Side: | Royal Black 6 mm |
| Front Right Side: | Royal Black 6 mm | Rear Right Side: | Royal Black 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 24/10/2022 | |
| Date Inspected: | 27/07/2022 | Inspected At: QAS AUTO PTE LTD (HQ) 3018A Ubi Road 1, #01-23 Singapore 408711 |
| Estimated Period of Repair: | 7.0 days | |

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00
-\$6,000.00

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | (Last Synchronised: 04 Nov 2022) | |
| Parts: | N/A | TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBK3483M) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >