

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007122/EVY3M4**Date:** 12/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00123472100	
Claimant Vehicle No :	SLP4878G	Insured Vehicle No :	YQ4399M	
Date of Loss:	24/07/2022	Nature of Claim:	TP	Claim No: SNM22D205188/C02/KAHLEONG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP4878G		Engine No:	2NRX159370
Make & Model:	TOYOTA VIOS, 1.5 (A)		Chassis No:	MHFB29F3002011985
Reg. Date:	07/06/2017 (Man. Year: 2017)		Odometer:	355719 km
Colour:	Grey			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,757.00	4,402.70	1,354.30	23.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,460.00	7,790.00	1,670.00	17.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,217.00	12,192.70	3,024.30	19.87
+ GST 7.00/7.00% (\$\$)	1,065.19	853.49	211.70	19.87
Nett Amount (\$\$)	16,282.19	13,046.19	3,236.00	19.87

INSPECTION

Date of Assignment:	03/08/2022		
Date Inspected:	27/07/2022	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	8.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP4878G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REINFORCEMENT SUB-AS	Dented	360.10 FS	*360.10 FS
2	1		*SEAL, RR BUMPER SIDE	Not Necessary	65.00 FS	*- FS
3	1		*SEAL, RR BUMPER SIDE	Not Necessary	65.00 FS	*- FS
4	1		*SUPPORT, RR BUMPER S (N/S)	Broken	25.00 FS	*25.00 FS
5	1		*SUPPORT, RR BUMPER S	Not Necessary	25.00 FS	*- FS
6	1		*RETAINER, RR BUMPER (N/S)	Broken	129.90 FS	*129.90 FS
7	1		*RETAINER, RR BUMPER	Not Necessary	129.90 FS	*- FS
8	1		*COVER, RR BUMPER, L	Broken	565.60 FS	*565.60 FS
9	4		*PIECE, RR BUMPER	Necessary	18.00 FS	*18.00 FS
10	1		*PANEL SUB-ASSY, BODY	Dented	775.70 FS	*775.70 FS
11	1		*TROUGH SUB-ASSY, LUG	Repair	161.70 FS	*- FS
12	1		*TROUGH SUB-ASSY, LUG	Bent	161.70 FS	*161.70 FS
13	1		*ARM SUB-ASSY, LUG CO	Bent	65.00 FS	*65.00 FS
14	1		*PANEL SUB-ASSY, LUGG	Dented	852.90 FS	*852.90 FS
15	1		*WEATHERSTRIP, LUGGAG	Crushed	190.10 FS	*190.10 FS
16	1		*LOCK ASSY, LUGGAGE C	Not Necessary	101.80 FS	*- FS
17	1		*PLATE, RR FLOOR FINI	Crushed	261.60 FS	*261.60 FS
18	1		*PLATE, LUGGAGE COMPT	Necessary	49.40 FS	*49.40 FS
19	1		*EMBLEM, SYMBOL	Necessary	57.50 FS	*57.50 FS
20	1		*PLATE, LUGGAGE COMPT	Necessary	38.50 FS	*38.50 FS
21	1		*GARNISH S/A LUG COMP	Broken	184.20 FS	*184.20 FS
22	1		*LAMP ASSY, RR COMBIN	Not Necessary	345.90 FS	*- FS
23	1		*LAMP ASSY, RR COMBIN (N/S)	Broken	345.90 FS	*345.90 FS
24	1		*LAMP ASSY, RR, RH	Not Necessary	205.00 FS	*- FS
25	1		*LAMP ASSY, RR, LH	Not Necessary	205.00 FS	*- FS
26	1		*BACK SENSOR GREY METALLIC	Broken	173.10 FS	*173.10 FS
27	1		*ARM SUB-ASSY, LUG CO	Bent	65.00 FS	*65.00 FS
28	1		*CARRIER ASSY, SPARE	Broken	33.50 FS	*33.50 FS
29	1		*SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,757.00	4,402.70
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND CONDUCT LEAK TEST	New	180.00	180.00
2	TRANSFER BOOTLID MECHANISM AND REVERSE C	New	540.00	540.00
3	R/I INTERIOR TRIMMING TO FAC REPAIR	New	360.00	360.00
4	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
5	SUPPLY SEALANT (NETT)2 PANEL	New	160.00	160.00
6	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	180.00
7	REPL ACC AFF PARTS AND PANEL	New	4,320.00	3,240.00
8	RESPRAY ACC AFF AREA	New	3,540.00	2,950.00
Gross Labour Cost (\$)			9,460.00	7,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >