

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007123/APA3Q2**Date:** 16/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220022419
Claimant Vehicle No :	SKW2154A	Insured Vehicle No :	GBL7444U
Date of Loss:	24/06/2022	Nature of Claim:	TP
		Claim No:	4940873357SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW2154A		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2186508A
Reg. Date:	22/10/2015 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1477865
Colour:	Grey	Odometer:	159337 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,214.70	494.79	719.91	59.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	650.00	500.00	43.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,364.70	1,144.79	1,219.91	51.59
Approved Total (Overridden) (S\$)		900.00		
(S\$)	2,364.70	900.00	1,464.70	61.94
+ GST 7.00/7.00% (S\$)	165.53	63.00	102.53	61.94
Nett Amount (S\$)	2,530.23	963.00	1,567.23	61.94
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,065.00		

INSPECTION

Date of Assignment:	24/08/2022	
Date Inspected:	24/08/2022	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	755.40 FN	*- FN
2	1		*REAR BUMPER SIDE HOLDER-LH	Not Necessary	44.50 FN	*- FN
3	1		*REAR FENDER ARC GARNISH -LH	Cut	483.10 FN	*483.10 FN
4	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	1		*SET REAR FENDER ARC GARNISH CLIPS -LH	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	1,343.00 543.10
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	128.30 48.31
					Total Parts (\$\$)	1,214.70 494.79

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR LH PORTION & RENEW ABOVE PARTS	New	400.00	200.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	600.00	400.00
3	TO CHECK WIRING	New	50.00	0.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			1,150.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >