

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SKQ2330P

Yr Regn: _____

13/1/14

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Volkswagen Jetta

c.c

1390

Colour: _____

Black

A/C: _____

Insured / Std / Nil / NA

Sp. Reading _____

104049

T/Radio: _____

Insured / Std / Nil / NA

Eng/No: _____

C/No: _____

WVW222672M058897

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRM / STD A/RM or

Tyre Size: _____

F: _____

195/55 R16

R: _____

71

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

16/7/22

D.O.I. _____

21/7/22

Survey held at _____

ARC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-34K

Order/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L&C: (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-394-TG

DATE : 27-Jul-2022

POLICY NO. :

VEHICLE REG. NO. : SKQ2330P

VEHICLE MAKE : VOLKSWAGEN JETTA 1.4 TSI A/T ABS D,

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / DD	1	\$ 1,600.19	\$ 1,600.19
2	Rear Bumper Side Retainer LH/RH	2	\$ 280.71	\$ 561.42
3	Rear Bumper Reinforcement	1	\$ 1,100.71	\$ 1,100.71
4	Rear Bumper Lower Garnish / CM	1	\$ 1,108.60	\$ 1,108.60
5	Rear Boot Emblem / MC	1	\$ 238.60	\$ 238.60
6	Rear Boot Logo (JETTA) / MC	1	\$ 189.77	\$ 189.77
7	Rear Boot Logo (TSI) / MC	1	\$ 189.77	\$ 189.77
8	Rear Tail Lamp LH / X	1	\$ 500.75	\$ 500.75
Parts Less 10%				\$ (548.98)
Total Spare Parts				\$ 4,940.83
SPECIAL NETT				
9	Rear Bumper Clips / MC	10	\$ 5.00	\$ 50.00
10	Reverse Sensor / Jh 10	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 250.00
LABOUR				
11	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 800.00	\$ 800.00
12	Spray Paint (Rear Bumper, Rear Boot, Rear End Panel)	1	\$ 800.00	\$ 800.00
13	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
14	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
15	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: James Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 1,810.00
Amount Before Excess	\$ 7,000.83
Add GST @ 7%	490.06
Total Amount Payable	\$ 7,490.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)
 27/7/22, 10.00am
 MC MC
 L/S
 by AL by
 4 dgt