



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22007128/Any3m4

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 12/10/2022

ATTN: ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBD 9103H	Veh. Inspected	CB 8125A
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1179729-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	26/07/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE COMMUTER	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GDH2232001077	Colour	SILVER
Odometer	186947 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	DURATURN	6 mm
L/H Front Tyre	195 R15C	DURATURN	6 mm
R/H Rear Tyre	195 R15C	DURATURN	6 mm
L/H Rear Tyre	195 R15C	DURATURN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/07/2022	Inspect Date / Time	26/07/2022 (01:40 PM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------