

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD	Ref:	CS3/INC22007131/Vvy3m4	
	189556	ROAD DE UNION HOUSESINGAPORE	Date:	25/08/2022	
	ATTN: JEFF LIN		Code:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YQ 4578M	Veh. Inspected	SMN 3560C	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1181459-001	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	26/07/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	JTDZS3EU20J038631	Colour	GREY	
	Odometer	110017 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	INTERTRAC	7 mm	
	L/H Front Tyre	205/60 R16	INTERTRAC	7 mm	
	R/H Rear Tyre	205/60 R16	INTERTRAC	7 mm	
	L/H Rear Tyre	205/60 R16	INTERTRAC	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information				
	Accident Date	22/07/2022	Inspect Date / Time	26/07/2022 (04:00 PM)	
	Survey held at	SV AUTOWORKS PTE LTD			
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC22007131/Vvy3m4

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

DEOD Auto Occupient OAE Licensed American

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$