

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007141/AQCE2**Date:** 30/11/2022REFERENCE

Insured/Claimant: ANG KIM HOCK Policy No:
Date of Loss: 12/07/2022 Nature of Claim: OD Claim No: 5519979783SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT4166U**
Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A) Engine No: CVK086932
Reg. Date: 10/06/2020 (Man. Year: 2019) Chassis No: WAUZZZF46KA110993
Colour: Black Odometer: 40887 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$158,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 18,658.00 | 13,181.20 | 5,476.80 | 29.35 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,422.00 | 4,072.00 | 2,350.00 | 36.59 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 25,080.00 | 17,253.20 | 7,826.80 | 31.21 |
| - Excess (S\$) | 550.00 | 550.00 | 0.00 | 0.00 |
| (S\$) | 24,530.00 | 16,703.20 | 7,826.80 | 31.91 |
| + GST 7.00/7.00% (S\$) | 1,717.10 | 1,169.22 | 547.88 | 31.91 |
| Nett Amount (S\$) | 26,247.10 | 17,872.42 | 8,374.68 | 31.91 |

INSPECTION

Date of Assignment: 27/07/2022
Date Inspected: 19/07/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|--|---------------|-------------|--------------|
| 1 | 1 | *FRONT BUMPER | Distorted | 2,377.00 FS | *1,901.60 FS |
| 2 | 1 | *FRONT BUMPER GRILLE - CENTER | Not Necessary | 219.00 FS | *- FS |
| 3 | 1 | *FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | Torn | 254.00 FS | *203.20 FS |
| 4 | 1 | *FRONT AIR GUIDE - RH | Missing | 72.00 FS | *57.20 FS |
| 5 | 1 | *FRONT AIR GUIDE GRILLE - RH | Missing | 151.00 FS | *120.40 FS |
| 6 | 1 | *FRONT BUMPER GUIDE SECTION - RH | Cracked | 41.00 FS | *32.24 FS |
| 7 | 1 | *FRONT BUMPER FOAM FILLER PIECE | Not Necessary | 139.00 FS | *- FS |
| 8 | 1 | *FRONT BUMPER REINFORCEMENT BEAM | Not Necessary | 899.00 FS | *- FS |
| 9 | 1 | *LOCK CARRIER TOP BRACKET | Not Necessary | 154.00 FS | *- FS |
| 10 | 1 | *FRONT PARKING AID SENSOR - INNER / OUTER | Missing | 265.00 FS | *212.00 FS |
| 11 | 4 | *FRONT PARKING AID SEAL RING | Necessary | 10.00 FS | *8.00 FS |
| 12 | 1 | *FRONT FENDER - RH | Dented | 861.00 FS | *688.80 FS |
| 13 | 1 | *FRONT FENDER CLOSING ELEMENT - RH | Not Necessary | 81.00 FS | *- FS |
| 14 | 1 | *FRONT FENDER BRACKET - RH | Not Necessary | 41.00 FS | *- FS |
| 15 | 1 | *FRONT FENDER RIVET (6PCS) | Necessary | 23.00 FS | *18.24 FS |
| 16 | 1 | *FRONT FENDER BRACE - RH | Not Necessary | 132.00 FS | *- FS |
| 17 | 1 | *FRONT WHEEL SPOILER - RH | Torn | 82.00 FS | *65.12 FS |
| 18 | 1 | *FRONT WHEEL SPOILER TRIM - RH | Torn | 40.00 FS | *32.00 FS |
| 19 | 1 | *FRONT STONE CHIP GUARD - RH | Not Necessary | 57.00 FS | *- FS |
| 20 | 1 | *FRONT WHEEL HOUSING LINER - RH | Torn | 262.00 FS | *209.60 FS |
| 21 | 1 | *FRONT AND REAR WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 149.00 FS | *- FS |
| 22 | 1 | *FRONT HEADLIGHT - RH | Cut | 8,293.00 FS | *6,635.20 FS |
| 23 | 1 | *FRONT HEADLIGHT LIFT CYLINDER - RH | Damaged | 231.00 FS | *184.40 FS |
| 24 | 1 | *FRONT HEADLIGHT BRACKET | Not Necessary | 7.00 FS | *- FS |
| 25 | 1 | *BONNET | Dented | 3,425.00 FS | *2,740.00 FS |
| 26 | 3 | *BONNET IMPACT PROTECTION - LH / RH / CENTER | Necessary | 93.00 FS | *73.20 FS |
| 27 | 1 | *SUNDRIES | Not Necessary | 300.00 FS | *- FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 18,658.00 13,181.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE | New | 350.00 | 250.00 |
| 2 | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS HEADLIGHT AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 2,800.00 | 1,500.00 |
| 3 | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET | New | 2,600.00 | 1,650.00 |
| 4 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| 5 | TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY | New | 480.00 | 480.00 |
| Gross Labour Cost (\$\$) | | | 6,422.00 | 4,072.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >