



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBA 3690J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	DAMAGED	65.00	65.00
1	N/S FORK TUBE ASSY }	DAMAGED	680.00	480.00
1	O/S FORK TUBE ASSY }	DAMAGED	680.00	-
1	FORK UNDER BRACKET	DAMAGED	145.00	145.00
1	FORK UPPER BRACKET	SERVICEABLE	155.00	-
1	FRONT BRAKE DISC	DAMAGED	155.00	155.00
1	FRONT RIM ASSY	TO REPAIR SEE LABOUR	750.00	-
1	TOP COWLING	DAMAGED	185.00	85.00
1	WINDSHIELD	DAMAGED	125.00	120.00
1	LAMP STAY	DAMAGED	50.00	50.00
1	LOWER COWLING	DAMAGED	58.00	58.00
1	HEADLAMP	DAMAGED	125.00	125.00
1	SET SIDE MIRROR	DAMAGED	120.00	70.00
2	FRONT SIGNALS	DAMAGED	80.00	80.00
2	HANDLE BARS	DAMAGED	136.00	120.00
1	SET HAND GRIP	DAMAGED	65.00	35.00
2	HANDLE BAR ENDS	DAMAGED	64.00	20.00
1	BRAKE LEVER	DAMAGED	38.00	38.00
1	CLUTCH LEVER	DAMAGED	38.00	38.00
1	METER ASSY	DAMAGED	750.00	420.00
1	FUEL TANK	DAMAGED	680.00	400.00
1	FRONT O/S FOOTREST	DAMAGED	85.00	85.00
1	FRONT O/S FOOTREST BRACKET	DAMAGED	115.00	55.00
1	BRAKE PEDAL	DAMAGED	32.00	32.00
1	REAR O/S FOOTREST	DAMAGED	28.00	28.00
1	EXHAUST PIPE ASSY	DAMAGED	1,350.00	480.00
1	EXHAUST PROTECTOR	DAMAGED	65.00	65.00
	LESS 10% DISCOUNT		-681.90	-324.90
			6,137.10	2,924.10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	DAMAGED	28.00	20.00
2	FORK OILS (SN)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN)	NECESSARY	56.00	56.00
1	SET STEERING CONE (SN)	NECESSARY	75.00	75.00
1	FRONT TYRE (SN) (\$150.00) (70%)	DAMAGED	300.00	105.00
			489.00	286.00
<u>LABOUR</u>				
	TO PROVIDE TOWING SERVICE.		50.00	40.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT RIM ASSY.		380.00	250.00
	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.		350.00	250.00
			860.00	570.00
GRAND TOTAL			7,486.10	3,780.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS3/ASM22001453/Rvy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.