

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Rep 9k.

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

) S + RS. \$

) Photos

) Others

TOTAL

3/8/22 4/5 @ 2400 in Rmnd Susan

s Brother Auto Engineering Workshop
1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbros@gmail.com

Tel: 67411730

ESTIMATE

res: AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way #07-16
AIG Building Singapore 079120

Ref Date: 27-07-2022
Ref No: GBJ1200G220725
Vehicle No: GBJ1200G
Model / Make: Mitsubishi
Capacity: 2998 cc FEA01BR1SDEK (CBU)

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front	Door 0/5 body 20	\$ 1,995.00	1	\$ 1,995.00		✓ 1815.20
2		Door Glass Regulator 0/5 11	\$ 627.90	1	\$ 627.90		X
3		Mirror Arm 0/5 11	\$ 545.20	1	\$ 545.20		X
4		Corner Panel 0/5 11	\$ 486.90	1	\$ 486.90		X
5		Corner Panel Clips 1 set 0/5 11	\$ 28.00	1	\$ 28.00	SN	X
6		Signal Lamp 0/5 208.21 320	\$ 324.30	1	\$ 324.30		✓
7		Head Lamp 0/5 11	\$ 856.40	1	\$ 856.40		X
8	front	Head Lamp Side Cover (amp 0/5 187 11)	\$ 295.40	1	\$ 295.40		✓
9		Bumper Side 0/5 319.82 11	\$ 441.70	1	\$ 441.70		✓ 252
10		Bumper Side Clips 1 set 11	\$ 65.00	1	\$ 65.00	SN	X
11		To check all wiring & electrical component for proper function			\$ 50.00	-	20
12		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 600.00	-	320
13		To putty & spray painting & including touch up paint on accident affected areas			\$ 500.00		300
14		To remove, replace and transfer door panel, fitting and mechanisms			\$ 80.00	-	60

Total Parts & Labour of estimate for damaged vehicle

\$ 6,815.80

Total amount in Lumpsum Basis for repaired vehicle

\$ -

SDL

Liu's Bro Auto Engrg Wks

not Allowed
27/7/22
L/S \$ 2400
4 days
whp. Ashu

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

23075.41
252
2306.57
700
3006.57
202
2405.57