

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22007155/EQY3Q2**Date:** 14/09/2022**REFERENCE**

Insured/Claimant: FARISUDIN BIN MOHAMED KASSIM Policy No: SP2000532132-01
Date of Loss: 18/07/2022 Nature of Claim: OD Claim No: 202222005711JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ2271C**
Make & Model: HYUNDAI AD AVANTE, 1.6 GLS (A) Engine No: G4FGKU244087
Reg. Date: 01/11/2019 (Man. Year: 2019) Chassis No: KMHD841CMLU995414
Colour: Beige Odometer: 73414 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$83,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm
Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,170.60	2,989.80	1,180.80	28.31
Miscellaneous Items	400.00	0.00	400.00	100.00
Labour	1,200.00	400.00	800.00	66.67
Paintwork Labour	1,200.00	800.00	400.00	33.33
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,970.60	4,189.80	2,780.80	39.89
+ GST 7.00/7.00% (S\$)	487.94	293.29	194.65	39.89
Nett Amount (S\$)	7,458.54	4,483.09	2,975.45	39.89

INSPECTION

Date of Assignment: 27/07/2022 Present Location: Shu Fatt Auto Works (HQ)
Date Inspected: 27/07/2022 Inspected At: Shu Fatt Auto Works (HQ)
Estimated Period of Repair: 5.0 days Block 1009 Bukit Merah Lane 3, #01-90
Singapore 159723

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2022)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ2271C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet	Dented	600.00 F	*600.00 F
2	1		*Front bonnet insulator	Not Necessary	105.00 F	*- F
3	12		*Front bonnet insulator clips	Not Necessary	36.00 F	*- F
4	1		*Front bonnet lock	Not Necessary	70.00 F	*- F
5	1		*Left front bonnet hinge	Bent	35.00 F	*36.00 F
6	1		*Right front bonnet hinge	Bent	35.00 F	*36.00 F
7	1		*Left front headlight	Broken	500.00 F	*520.00 F
8	1		*Right front headlight	Broken	500.00 F	*520.00 F
9	1		*Front grille	Broken	280.00 F	*280.00 F
10	1		*Front grille emblem	Not Necessary	30.00 F	*- F
11	8		*Front grille clips	Not Necessary	24.00 F	*- F
12	1		*Front bumper	Broken	360.00 F	*430.00 F
13	1		*Front bumper top rubber	Crushed	20.00 F	*20.00 F
14	1		*Front bumper foam	Broken	65.00 F	*65.00 F
15	1		*Front bumper reinforcement	Not Necessary	240.00 F	*- F
16	16		*Front bumper clips	Not Necessary	48.00 F	*- F
17	1		*Left front bumper side retainers	Not Necessary	18.00 F	*- F
18	1		*Right front bumper side retainers	Not Necessary	18.00 F	*- F
19	1		*Front bumper lower garnish	Not Necessary	70.00 F	*- F
20	12		*Front bumper lower garnish clips	Not Necessary	36.00 F	*- F
21	1		*Front number plate garnish	Broken	60.00 F	*60.00 F
22	1		*Front support panel	Not Necessary	280.00 F	*- F
23	1		*Front support top garnish	Broken	45.00 F	*45.00 F
24	8		*Front support top garnish clips	Not Necessary	24.00 F	*- F
25	16		*Left front fender cowling clips	Not Necessary	48.00 F	*- F
26	16		*Right front fender cowling clips	Not Necessary	48.00 F	*- F
27	1		*Front air resonator	Not Necessary	65.00 F	*- F
28	1		*Coolant	Not Necessary	28.00 FS	*- FS
29	1		*Front number plate	Broken	55.00 FS	*55.00 FS
Supplementary #1						
30	1		*Right headlamp lower bracket	Broken	18.00 F	*18.00 F
31	1		*Left headlamp lower bracket	Broken	23.00 F	*23.00 F
32	1		*Right front bumper upper bracket	Broken	15.00 F	*15.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,799.00	2,723.00
+ Margin on L,N Items 10.00/10.00% (S\$)	371.60	266.80
Total Parts (S\$)	4,170.60	2,989.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	To remove, replace aircon condenser, fan assembly, fill air con freon & assembly.	150.00	0.00
2	1	To remove, replace radiator, fill coolant assembly.	250.00	0.00
Sub Total (\$\$)			400.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To respray damaged parts.	New	1,200.00	800.00
<u>Labour Items</u>				
2	To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt fender, left frt fender panel, rt frt fender panel, renew frt bonnet, frt support panel, frt lights, grille, frt bumper & assembly.	New	1,200.00	400.00
Gross Labour Cost (\$\$)			2,400.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >