

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007159/TCY3Q2**Date:** 21/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00077742202
Claimant Vehicle No :	SLV3423K	Insured Vehicle No :	GBJ1437R
Date of Loss:	15/07/2022	Nature of Claim: TP	Claim No: SNM22D205070/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3423K		
Make & Model:	PEUGEOT 3008 ACTIVE PURETECH, 1.2 EAT6 (A)	Engine No:	10XTA40859300
Reg. Date:	28/12/2017 (Man. Year: 2017)	Chassis No:	VF3MRHNYWHS312690
Colour:	White	Odometer:	73230 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,731.30	3,936.63	19,794.67	83.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,260.00	1,290.00	3,970.00	75.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,991.30	5,226.63	23,764.67	81.97
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	28,991.30	4,100.00	24,891.30	85.86

INSPECTION

Date of Assignment:	27/07/2022	
Date Inspected:	28/07/2022	Inspected At: BLK 8 KAKI BUKIT AVENUE 4 #02-16 PREMIER @ KAKI BUKIT SINGAPORE 415875 Repairer: PROMPT MOTORS PTE LTD (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	M1-SUV	PEUGEOT 3008 ACTIVE PURETECH 1.2 EAT6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV3423K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,345.00 FL	*- FL
2	1		*BONNET RH HINGE	Not Necessary	112.00 FL	*- FL
3	1		*BONNET LH HINGE	Not Necessary	112.00 FL	*- FL
4	1		*BONNET INSULATOR	Not Necessary	231.00 FL	*- FL
5	1		*BONNET LOCK	Not Necessary	98.00 FL	*- FL
6	1		*FRONT BUMPER	Deformed	1,487.00 FL	*1,450.00 FL
7	1		*FRONT BUMPER LH FOG LAMP	Not Necessary	288.00 FL	*- FL
8	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	153.00 FL	*- FL
9	1		*FRONT BUMPER LH FOG LAMP COVER CHROME	Not Necessary	99.00 FL	*- FL
10	1		*FRONT BUMPER LH GRILLE EMBLEM	Not Necessary	296.00 FL	*- FL
11	1		*FRONT BUMPER CENTRE LOWER GARNISH	Not Necessary	366.00 FL	*- FL
12	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	467.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	672.00 FL	*- FL
14	1		*FRONT BUMPER LOWER SNIFFENER	Not Necessary	302.00 FL	*- FL
15	1		*FRONT BUMPER INNER SPONGE	Not Necessary	233.00 FL	*- FL
16	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	98.00 FL	*- FL
17	1		*FRONT BUMPER LH SIDE RETAINER	Deformed	98.00 FL	*98.00 FL
18	1		*FRONT BUMPER INNER AIR GUIDE	Not Necessary	178.00 FL	*- FL
19	1		*FRONT BUMPER LOWER UNDER COVER	Not Necessary	308.00 FL	*- FL
20	1		*FRONT BUMPER RH AIR DUCT GUIDE	Not Necessary	155.00 FL	*- FL
21	1		*FRONT BUMPER LH AIR DUCT GUIDE	Not Necessary	155.00 FL	*- FL
22	1		*FRONT BUMPER LH INNER SIDE BRACKET	Not Necessary	167.00 FL	*- FL
23	1		*FRONT BUMPER LH PARKING SENSOR	Not Necessary	251.00 FL	*- FL
24	1		*FRONT CHROME GRILLE	Cracked	553.00 FL	*415.00 FL
25	1		*FRONT CHROME GRILLE EMBLEM	Not Necessary	96.00 FL	*- FL
26	1		*LH HEADLAMP	Cracked	2,080.00 FL	*1,755.00 FL
27	1		*RH HEADLAMP	Not Necessary	2,080.00 FL	*- FL
28	1		*FRONT LH FENDER	Repair	903.00 FL	*- FL
29	1		*FRONT LH FENDER QURTER GARNISH	Not Necessary	193.00 FL	*- FL
30	1		*FRONT LH FENDER ARCH MOULDING	Cut	488.00 FL	*297.00 FL
31	1		*FRONT LH FENDER SPLASH SHIELD	Not Necessary	176.00 FL	*- FL
32	1		*FRONT LH FENDER STRENGHTEN	Not Necessary	118.00 FL	*- FL
33	1		*FRONT LH FENDER ACCOUSTIC SEAL	Not Necessary	93.00 FL	*- FL
34	1		*FRONT LH FENDER BRACKET	Not Necessary	139.00 FL	*- FL
35	1		*FRONT LH FENDER UPPER GARNISH	Not Necessary	195.00 FL	*- FL
36	1		*SUPPORT PANEL TOP	Cracked	498.00 FL	*325.70 FL
37	1		*SUPPORT PANEL TOP GARNISH COVER	Not Necessary	387.00 FL	*- FL
38	1		*SUPPORT PANEL TOP INNER COVER	Not Necessary	377.00 FL	*- FL
39	1		*AIRCON CONDENSER	Not Necessary	731.00 FL	*- FL
40	1		*RADIATOR ASSY	Not Necessary	875.00 FL	*- FL
41	1		*FRONT LH WHEEL HUB	Not Necessary	603.00 FL	*- FL
42	1		*FRONT LH KNUCKLE ARM	Not Necessary	1,367.00 FL	*- FL
43	1		*FRONT LH WHEEL BEARING	Not Necessary	652.00 FL	*- FL
44	1		*FRONT LH LOWER ARM BALL JOINT	Not Necessary	321.00 FL	*- FL
45	1		*FRONT LH LOWER ARM	Not Necessary	667.00 FL	*- FL
46	1		*FRONT LH SHOCK ABSORBER	Not Necessary	581.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT LH STABILIZER BAR LINKAGE	Not Necessary	167.00 FL	*- FL
48	1		*FRONT LH TIE ROD END	Not Necessary	92.00 FL	*- FL
49	1		*FRONT LH FUSE BOX UPPER COVER	Not Necessary	159.00 FL	*- FL
50	1		*FRONT LH FUSE BOX LOWER COVER	Not Necessary	295.00 FL	*- FL
51	1		*SET BONNET INSULATOR CLIPS	Not Necessary	120.00 FS	*- FS
52	1		*BONNET SEAL	Not Necessary	100.00 FS	*- FS
53	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
54	1		*SET FRONT BUMPER LH GRILLE EMBLEM	Not Necessary	80.00 FS	*- FS
55	1		*SET FRONT BUMPER CENTRE LOWER GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
56	1		*SET FRONT LH FENDER RIVETS	Not Necessary	90.00 FS	*- FS
57	1		*SET FRONT CHROME GRILLE CLIPS	Not Necessary	100.00 FS	*- FS
58	1		*SET FRONT LH FENDER ARCH MOULDING CLIPS	Not Necessary	100.00 FS	*- FS
59	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
60	1		*SET SUPPORT PANEL TOP GARNISH COVER CLIPS	Not Necessary	80.00 FS	*- FS
61	1		*FRONT LH SPORT RIM	Not Necessary	1,550.00 FS	*- FS
62	1		*FRONT LH TYRE	Not Necessary	680.00 FS	*- FS
63	1		*BRAKE FLUID	Not Necessary	120.00 FS	*- FS
64	1		*RADIATOR COOLANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	25,987.00	4,370.70
- List Item Discount on L Items 10.00/10.00% (S\$)	2,255.70	434.07
Total Parts (S\$)	23,731.30	3,936.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES ON AFFECTED AREAS AND PANELS	New	1,600.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,500.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	30.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR .TO REFILL AIRCON GAS	New	280.00	0.00
6	REMOVE AND REPLACE RADIATOR ASSY ,PIPES AND HOSES TO ASSIST REPAIR .TO REFILL COOLANT	New	280.00	0.00
7	REFOCUS AND ADJUST HEADLAMPS ASSY	New	100.00	30.00
8	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM (BEFORE AND AFTER)	New	180.00	0.00
9	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	650.00	0.00
10	REMOVE AND REPLACE FRONT LH FUSE BOX AND TRNASFER WIRE HARNESS	New	450.00	0.00
Gross Labour Cost (S\$)			5,260.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >