

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22007162/Tvy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	01/08/2022		
	ATTN: ANG YVON	NE		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMU 9004R	Veh. Inspected	k	FBR 1980X	
	Policy No.	GA594501	Coverage (\$)		0.00	
	Claim No.	S2M046LS	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		27/07/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	YAMAHA R15	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	ME1RG525BK0062395	Colour		RED / BLACK	
	Odometer	102946 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/70 R17	PIRELLI		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70 R17	PIRELLI		5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS PORTION	HE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT ORTION				
5.	General Information					
	Accident Date	11/07/2022	Inspect Date /	Time	28/07/2022 (01:21 PM)	
	Survey held at S1 MOTORING BLK 3006 UBI ROAD 1 #01-366 SINGAPORE 408700					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b. Estimate Days of Repair						
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/ASM22007162/Tvy3e2

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser