

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22007168/UVY3E2

**Date:** 05/08/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00172552100		
<b>Claimant Vehicle No :</b>	SLZ9729T	<b>Insured Vehicle No :</b>	SKA2865Y		
Date of Loss:	24/07/2022	Nature of Claim:	TP	Claim No:	SNM22D205158/C02/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLZ9729T</b>	Engine No:	2NRX328155
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Chassis No:	MHFZ28H3300054153
Reg. Date:	24/05/2018 (Man. Year: 2018)	Odometer:	93461 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,302.15	5,449.00	7,853.15	59.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,150.00	2,780.00	70.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,232.15</b>	<b>6,599.00</b>	<b>10,633.15</b>	<b>61.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>17,232.15</b>	<b>5,200.00</b>	<b>12,032.15</b>	<b>69.82</b>

### INSPECTION

Date of Assignment:	27/07/2022	
Date Inspected:	27/07/2022 Inspected At:	15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre Repairer: Asia Motorsports Solution Pte Ltd (Kaki Bukit)
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2022)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ9729T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER ASSY	Distorted	1,285.60 FL	*486.10 FL
2	1	*FRONT BUMPER TOW HOOD COVER	Not Necessary	86.70 FL	*- FL
3	1	*FRONT LEFT BUMPER FOG LAMP COVER	Distorted	87.70 FL	*87.70 FL
4	1	*FRONT LEFT BUMPER FOG LAMP	Cracked	280.50 FL	*280.50 FL
5	1	*FRONT BUMPER CENTER LOWER GRILLE	Not Necessary	199.80 FL	*- FL
6	1	*FRONT BUMPER INNER FOAM	Not Necessary	127.90 FL	*- FL
7	1	*FRONT BUMPER SIDE RETAINERS	N/S Cracked	133.80 FL	*62.50 FL
8	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	330.90 FL	*- FL
9	2	*FRONT BUMPER BRACKETS	Not Necessary	122.70 FL	*- FL
10	1	*FRONT GRILLE ASSY	Not Necessary	298.40 FL	*- FL
11	1	*FRONT GRILLE EMBLEM	Not Necessary	67.80 FL	*- FL
12	1	*FRONT LEFT HEADLAMP ASSY	Scratched	3,063.10 FL	*3,063.10 FL
13	1	*FRONT LEFT SUSPENSION ASSY	Bent	1,232.50 FL	*382.70 FL
14	1	*FRONT LEFT KNUCKLE ARM	Bent	425.40 FL	*425.40 FL
15	1	*FRONT LEFT LOWER ARM	Bent	420.30 FL	*420.30 FL
16	1	*FRONT LEFT KNUCKLE ARM	Repeated	425.40 FL	*- FL
17	1	*FRONT LEFT WHEEL HUB WITH BEARING	Necessary	350.80 FL	*350.80 FL
18	1	*FRONT LEFT STABILIZER LINK	Bent	191.50 FL	*161.10 FL
19	1	*FRONT LEFT FENDER INNER SIDE GARNISH	Not Necessary	78.60 FL	*- FL
20	1	*FRONT LEFT FENDER	Dented / Bent	989.50 FL	*715.10 FL
21	1	*FRONT LEFT FENDER INNER SHIELD	Torn	176.70 FL	*176.70 FL
22	1	*FRONT LEFT BRAKE DISC	Not Necessary	225.60 FL	*- FL
23	1	*FRONT LEFT DOOR PANEL	Repair	1,461.30 FL	*- FL
24	1	*FRONT LEFT DOOR INNER LOCK MECHANISM	Not Necessary	250.80 FL	*- FL
25	1	*FRONT LEFT DOOR REGULATOR LINKAGE WITH MOTOR ASSY	Not Necessary	461.90 FL	*- FL
26	1	*FRONT LEFT DOOR OUTER HANDLE	Not Necessary	187.60 FL	*- FL
27	2	*FRONT LEFT DOOR HINGES	Not Necessary	166.20 FL	*- FL
28	1	*FRONT LEFT DOOR CHECKER LINKAGE	Not Necessary	168.90 FL	*- FL
29	1	*FRONT LEFT DOOR OUTER WEATHERSTRIP	Not Necessary	188.20 FL	*- FL
30	1	*FRONT BONNET ASSY	Not Necessary	1,452.30 FL	*- FL
31	1	*FRONT SUPPORT PANEL ASSY	Not Necessary	997.80 FL	*- FL
32	1	*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
33	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
34	6	*FRONT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
35	8	*FRONT LOWER GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
36	1	*FRONT LEFT WHEEL RIM	Warped	780.00 FS	*400.00 FS
37	1	*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
38	1	*SET FRONT LEFT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>17,286.20</b>	<b>7,102.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>3,984.05</b>	<b>1,653.00</b>
<b>Total Parts (S\$)</b>	<b>13,302.15</b>	<b>5,449.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT LEFT AFFECTED AREA AND REPLACE FRONT LEFT DAMAGED PARTS	New	1,400.00	300.00
2	TO PUTTY AND SPRAY PAINTING FRONT LEFT AND FRONT PORTION	New	1,400.00	600.00
3	TO CHECK AND FOCUS FRONT LIGHTING AND WIRING	New	50.00	20.00
4	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AND FRONT AFFECTED AREA	New	140.00	30.00
5	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS	New	350.00	120.00
6	TO BALANCE FRONT LEFT WHEEL	New	50.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
8	TO REMOVE AND INSTALL FRONT LEFT DOOR LOCK MECHANISM	New	80.00	0.00
9	TO CHECK REAR RIGHT DOOR CENTRAL LOCKING FOR FUNCTION	New	80.00	0.00
10	TO TRANSFER FRONT LEFT DOOR GLASS TO NEW DOOR	New	80.00	0.00
11	TO REMOVE AND INSTALL FRONT LEFT DOOR REGULATOR WITH MOTOR ASSY	New	80.00	0.00
12	TOWING SERVICE	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,930.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >