

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22007174/TCY3Q2**Date:** 26/09/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000793
Claimant Vehicle No :	SHC264U	Insured Vehicle No :	SMQ4762P
Date of Loss:	26/07/2022	Nature of Claim:	TP
		Claim No:	M2203942

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC264U	Engine No:	G4LEJU191284
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVKU141289
Reg. Date:	30/04/2019 (Man. Year: 2018)	Odometer:	417366 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Excellent	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,944.48	981.12	963.36	49.54
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,020.00	630.00	390.00	38.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,975.48	1,622.12	1,353.36	45.48
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	2,975.48	1,100.00	1,875.48	63.03
+ GST 7.00/7.00% (S\$)	208.28	77.00	131.28	63.03
Nett Amount (S\$)	3,183.76	1,177.00	2,006.76	63.03

INSPECTION

Date of Assignment:	27/07/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	27/07/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2022)
Parts: 143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC264U)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	2		*REAR BUMPER SIDE BRACKET LH/RH	Not Necessary	111.60 FL	*- FL
3	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	194.80 FL	*- FL
5	2		*REAR BUMPER REINFORCEMENT STAY LH/RH	Not Necessary	276.20 FL	*- FL
6	1		*REAR BUMPER LOWER MOULDING	Not Necessary	155.00 FL	*- FL
7	1		*REAR CENTRE LOWER COVER	Not Necessary	225.00 FL	*- FL
8	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
9	1		*REAR BUMPER FOG LAMP	Not Necessary	201.10 FL	*- FL
10	1		*REAR NUMBER PLATE W/HOLDER	Cracked	55.00 FS	*55.00 FS
11	1		*REAR REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
12	1		*BOOT LID SMART KEY SENSOR	Not Necessary	40.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,371.85	1,167.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	427.37	186.53
Total Parts (\$\$)	1,944.48	981.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOVE/REFI XREVERSE SENSOR	New	60.00	30.00
4	TUFF COATING	New	60.00	0.00
Gross Labour Cost (\$\$)			1,020.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >