

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22007177/Tvy3m4	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	04/08/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBA 9054G	Veh. Inspected	ł	SKC 988D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/026075	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		27/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA CX-5	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JM6KF2W7AK0318031	Colour		BLUE	
	Odometer	35456 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/65 R17	YOKOHAMA		6 mm	
	L/H Front Tyre	225/65 R17	YOKOHAMA		6 mm	
	R/H Rear Tyre	225/65 R17	YOKOHAMA		6 mm	
	L/H Rear Tyre	225/65 R17	YOKOHAMA		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.						
	Accident Date	26/07/2022	Inspect Date /	Time	27/07/2022 (03:40 PM)	
	Survey held at	CHIP SOON AUTO SUPPLY CO.				
		BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22007177/Tvy3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser