

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22007188/KVY3E2
Date: 17/08/2022

REFERENCE

Insured/Claimant: BIS MOTORING PTE LTD Policy No: MCF22A00000100
Date of Loss: 26/07/2022 Nature of Claim: OD Claim No: DMCF2200152H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ1610B**
Make & Model: OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 Turbo (A) Engine No: A2183178JSUX0332
Reg. Date: 25/02/2019 (Man. Year: 2019) Chassis No: W0VZM6EF8K1034539
Colour: Red Odometer: 258422 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$108,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: APLUS 7 mm Rear Left Side: Vinmax 8 mm
Front Right Side: APLUS 7 mm Rear Right Side: Vinmax 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,358.80	4,147.00	5,211.80	55.69
Miscellaneous Items	84.00	84.00	0.00	0.00
Labour	2,440.00	830.00	1,610.00	65.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,882.80	5,061.00	6,821.80	57.41
Approved Total (Overridden) (S\$)		3,450.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	9,882.80	1,450.00	8,432.80	85.33
+ GST 7.00/7.00% (S\$)	691.80	101.50	590.30	85.33
Nett Amount (S\$)	10,574.60	1,551.50	9,023.10	85.33

INSPECTION

Date of Assignment: 27/07/2022 Present Location: Munich Autocare Pte Ltd (HQ)
Date Inspected: 28/07/2022 Inspected At: Munich Autocare Pte Ltd (HQ)
Estimated Period of Repair: 4.0 days 60 Jalan Lam Huat, #07-43
Singapore 737869

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Aug 2022)

Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ1610B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	39214206	*FRONT BONNET (WCP)	Repair	1,705.00 F	*- F
2	1	39118540	*FRONT BONNET LOCK (WCP)	Repair	43.00 F	*- F
3	1	39143307	*FRONT BONNET LOCK BRACKET (WCP)	Repair	127.00 F	*- F
4	1	39114984	*FRONT RADIATOR GRILLE TOP GARNISH (WCP)	Serviceable	40.00 F	*- F
5	1	39197502	*FRONT RADIATOR TOP INNER GARNISH (WCP)	Distorted	141.00 F	*141.00 F
6	1	39107929	*RADIATOR GRILLE (WCP)	Cracked	384.00 F	*384.00 F
7	1	13491196	*RADIATOR GRILLE MOULDING (CHROME) (WCP)	Cracked	391.00 F	*391.00 F
8	1	13491204	*FRONT LOGO EMBLEM (WCP)	Necessary	75.00 F	*75.00 F
9	1	39210099	*FRONT HEADLAMP LH (WCP)	Serviceable	1,055.00 F	*- F
10	1	39210100	*FRONT HEADLAMP LR (WCP)	Cracked	1,055.00 F	*1,055.00 F
11	1	13491383	*FRONT HEADLAMP LOWER BRACKET LH (WCP)	Serviceable	60.00 F	*- F
12	1	13491381	*FRONT HEADLAMP LOWER BRACKET RH (WCP)	Repair	60.00 F	*- F
13	1	39108221	*FRONT BUMPER LOWER GRILLE (WCP)	Serviceable	120.00 F	*- F
14	1	39159651	*FRONT BUMPER (WCP)	Cracked	1,158.00 F	*1,158.00 F
15	1	1349119013491191	*FRONT RADIATOR GRILLE MOULDING LH/RH (CHROME) (WCP)	Serviceable	270.00 F	*- F
16	1	39098178	*FRONT BUMPER SPONGE (WCP)	Cracked	107.00 F	*107.00 F
17	1	39117745	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	459.00 F	*459.00 F
18	1	39108219	*FRONT BUMPER LOWER LIP GARNISH LH (WCP)	Serviceable	65.00 F	*- F
19	1	39108220	*FRONT BUMPER LOWER LIP GARNISH RH (WCP)	Serviceable	65.00 F	*- F
20	1	39020290	*FRONT BUMPER MOULDING RH (WCP)	Serviceable	70.00 F	*- F
21	1	39020289	*FRONT BUMPER MOULDING LH (WCP)	Serviceable	70.00 F	*- F
22	1	39143306	*FRONT SUPPORT PANEL (WCP)	Repair	258.00 F	*- F
23	1	39077621	*FRONT UPPER SUPPORT PANEL (WCP)	Repair	170.00 F	*- F
24	1	95515167	*FRONT PARKING SENSOR (WCP)	Serviceable	410.00 F	*- F
25	1	13238718	*FRONT BUMPER SENSOR HARNESS WIRE (WCP)	Serviceable	150.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	8,508.00	3,770.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	850.80	377.00

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	42.00	42.00
2	1	FRONT RADIATOR TOP GARNISH CLIPS (NECESSARY)	42.00	42.00
Sub Total (\$\$)			84.00	84.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER, SUPPORT PANEL ,CHASSIS LH/RH AND ALL DAMAGE AREAS	New	1,200.00	350.00
2	TO CHECK ALL WIRING FOR PROPER FUNCTION AND PARKING SENSOR FOR OPERATION	New	120.00	60.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH , FOG LAMP LH/RH FOCUS	New	120.00	20.00
4	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER , FRONT BUMPER, SUPPORT PANEL , AND POLISH ALL DAMAGE AREAS	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,440.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >