

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. GBC 3073E

Qty	Description of Parts	Condition	Recommended (\$)
	REPLACEMENT OF PARTS		
1	REAR DOOR	DENTED	1,339.25
1	TAILLAMP LH	сит	245.00
1	TAILLAMP RH	сит	245.00
4	REAR DOOR HINGE @\$55.00	BENT	220.00
1	REAR DOOR LOWER PANEL	DENTED	727.43
1	REAR DOOR LOCK LH	BENT	106.00
1	FRONT BUMPER	DENTED	645.30
2	FRONT BUMPER BRACKET @\$191.00	BENT	382.00
1	FRONT GRILLE	BROKEN	517.00
1	FRONT PANEL	DENTED	1,144.00
1	FRONT PANEL CENTRE GARNISH (BLACK)	CUT	279.30
	LESS 25% DISCOUNT		-1,462.57
			4,387.71
	SPECIAL NETT ITEMS		
1	70KM/H STICKER (SN)	NECESSARY	20.00
1	13 PERSON STICKER (SN)	NECESSARY	20.00
1	REAR DOOR ALUMINIUM PANEL (SN)	BENT	900.00
1	FRONT LOGO (SN)	NECESSARY	72.00
1	FRONT (DYNA) LOGO (SN)	NECESSARY	61.00
1	ELECTRICAL CHECKING (SN)	NECESSARY	30.00
1	SEALANT (SN)	NECESSARY	40.00
1	UNDERSEAL (SN)	NECESSARY	30.00
1	NUMBER PLATE FRONT (SN)	NECESSARY	35.00
1	NUMBER PLATE REAR & BRACKET (SN)	BENT	150.00
			1,358.00
	LABOUR		
	FRONT PORTION LABOUR.		800.00
	REAR PORTION LABOUR.		800.00
	FRONT PORTION SPRAY.		400.00
	REAR PORTION SPRAY.		600.00
			2,600.00
	GRAND TOTAL		8,345.71

Report Ref No. CS3/SPF22007193/Ecy3e2





RECOMMENDED COST OF LUMP SUM REPAIRS	6,650.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/SPF22007193/Ecy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$6,650-\$7,650

CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser