



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF22007193/Ecy3e2

ACCIDENT CLAIMS SECTION(SPORE POLICE
FORCE)POLICE LOGISTICS BASE (PLB)1
HEMMANT ROAD SINGAPORE 438675

Date: 31/08/2022

ATTN: HAFIZUL FARHAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|---------------------|----------------------|-----------------------|------------|
| Insured Veh. | GBB 7823L | Veh. Inspected | GBC 3073E |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | ACS/105/009/2022/045 | Excess (\$) | 0.00 |
| Assign From | HAFIZUL FARHAN | Assign Date | 28/07/2022 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|--------------------|
| Make & Model | TOYOTA DYNA 150 | c.c | 2982 |
| Engine No. | HIDDEN | Year of Reg. | 2011 |
| Chassis No. | JTFAT35Y70K201787 | Colour | SILVER |
| Odometer | 294671 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|----------|----------|---------|
| R/H Front Tyre | 195 R15C | GOODYEAR | 4 mm |
| L/H Front Tyre | 195 R15C | GOODYEAR | 4 mm |
| R/H Rear Tyre | 195 R15C | GOODYEAR | 4 mm |
| L/H Rear Tyre | 195 R15C | GOODYEAR | 4 mm |

4. Description of Damages

| | |
|--|--|
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS. |
|--|--|

5. General Information

| | | | |
|-----------------------|--|----------------------------|-------------------------|
| Accident Date | 25/07/2022 | Inspect Date / Time | 28/07/2022 (12:27 PM) |
| Survey held at | NGEE NGEE MOTOR BLK 1 NO: 22 PANDAN LOOP SINGAPORE 128219 | | |

5a. Remarks

| | |
|--|--|
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|--|

5b. Estimate Days of Repair

| | |
|--|------------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 10 Working Days |
|--|------------------------|