

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007196/EQCE2**Date:** 16/11/2022**REFERENCE**

Insured/Claimant:	RISHAB MUKHERJEE	Policy No:	2100462077	
Date of Loss:	26/07/2022	Nature of Claim:	OD	Claim No: 6148698836SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB9706K	Engine No:	CVN006626
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF41GA048197
Reg. Date:	27/04/2016 (Man. Year: 2016)	Odometer:	45888 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,500.00	19,920.40	15,579.60	43.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,694.00	9,379.00	5,315.00	36.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,194.00	29,299.40	20,894.60	41.63
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	49,894.00	28,999.40	20,894.60	41.88
+ GST 7.00/7.00% (S\$)	3,492.58	2,029.96	1,462.62	41.88
Nett Amount (S\$)	53,386.58	31,029.36	22,357.22	41.88

INSPECTION

Date of Assignment:	28/07/2022	
Date Inspected:	28/07/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	10.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	612.00 FS	*489.60 FS
3	1		*FRONT BUMPER SECURING STRIP (2PCS)	Broken(1Pc Only)	79.00 FS	*31.60 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Crushed	254.00 FS	*203.20 FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Broken	72.00 FS	*57.20 FS
7	1		*RADIATOR GRILLE	Broken	1,277.00 FS	*1,021.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	151.00 FS	*120.40 FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	139.00 FS	*110.80 FS
10	1		*FRONT REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
11	1		*FRONT BUMPER GUIDE SECTION - LH	Broken	41.00 FS	*32.24 FS
12	1		*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
13	1		*SIGN CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
14	1		*STICKER FOR AIR CONDITIONER	Necessary	9.00 FS	*6.64 FS
15	1		*FRONT REINFORCEMENT BEAM BRACKET - LH	Bent	254.00 FS	*203.20 FS
16	1		*FRONT LOCK CARRIER BRACKET	Broken	154.00 FS	*122.80 FS
17	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
18	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
19	1		*HORN - LH	Not Necessary	134.00 FS	*- FS
20	1		*HORN BRACKET - LH	Not Necessary	33.00 FS	*- FS
21	1		*FRONT FENDER - LH	Dented	861.00 FS	*688.80 FS
22	1		*FENDER ATTACHMENT PART	Not Necessary	211.00 FS	*- FS
23	1		*FRONT FENDER CLOSING ELEMENT - LH	Necessary	81.00 FS	*64.24 FS
24	1		*FRONT FENDER BRACKET - LH FRONT	Bent	41.00 FS	*32.72 FS
25	1		*FRONT FENDER BRACE - LH	Bent	132.00 FS	*105.20 FS
26	1		*FRONT FENDER BRACKET - LH	Bent	55.00 FS	*44.00 FS
27	1		*FRONT FENDER BRACKET - LH CENTER	Bent	36.00 FS	*28.08 FS
28	1		*FRONT FENDER CLOSING ELEMENT - LH REAR	Not Necessary	37.00 FS	*- FS
29	1		*FRONT FENDER SIDE COVER - LH	Not Necessary	13.00 FS	*- FS
30	1		*FRONT FENDER POP RIVET (7PCS)	Necessary	27.00 FS	*21.28 FS
31	1		*FRONT WHEEL HOUSING LINER - LH	Crushed	260.00 FS	*208.00 FS
32	1		*WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	219.00 FS	*- FS
33	1		*FRONT WHEEL SPOILER - LH	Broken	82.00 FS	*65.12 FS
34	1		*FRONT WHEEL SPOILER TRIM - LH	Not Necessary	39.00 FS	*- FS
35	1		*FRONT FENDER STONE CHIP GUARD - LH	Necessary	57.00 FS	*45.28 FS
36	1		*FRONT FENDER LEDGE COVER - FRONT	Missing	35.00 FS	*27.52 FS
37	1		*FRONT FENDER LEDGE COVER - LH OUTER	Crushed	26.00 FS	*20.16 FS
38	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
39	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
40	2		*BONNET HINGE - LH / RH	Not Necessary	680.00 FS	*- FS
41	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
42	1		*BONNET HINGE COVER	Not Necessary	68.00 FS	*- FS
43	2		*BONNET GAS FILLED STRUT	Not Necessary	512.00 FS	*- FS
44	1		*BONNET STRIKER	Bent	56.00 FS	*44.56 FS
45	1		*BONNET LOCK	Bent	228.00 FS	*182.00 FS
46	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
47	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
48	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
49	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
50	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*PLENUM CHAMBER COVER	Not Necessary	108.00 FS	*- FS
52	1		*BONNET SOUND ABSORBER	Crushed	382.00 FS	*305.60 FS
53	1		*LED HEADLIGHT - LH	Broken	8,294.00 FS	*6,635.20 FS
54	1		*HEADLIGHT POWER MODULE	Broken	840.00 FS	*673.60 FS
55	1		*HEADLIGHT CONTROL UNIT	Broken	840.00 FS	*672.00 FS
56	1		*HEADLIGHT HOSE - LH	Crushed	42.00 FS	*32.88 FS
57	3		*HEADLIGHT COMPENSATION PIECE	Bent	135.00 FS	*108.00 FS
58	1		*HEADLIGHT WASH CYLINDER - LH	Broken	231.00 FS	*184.40 FS
59	1		*HEADLIGHT WASH CYLINDER BRACKET - LH	Necessary	7.00 FS	*5.44 FS
60	1		*WASHER HOSE	Not Necessary	107.00 FS	*- FS
61	1		*FRONT LOCK CARRIER	Broken	1,127.00 FS	*901.60 FS
62	2		*RADIATOR SUPPORT - LH / RH	Not Necessary	86.00 FS	*- FS
63	1		*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
64	1		*REFRIGERANT LINE	Not Necessary	186.00 FS	*- FS
65	1		*REFRIGERANT LINE	Not Necessary	381.00 FS	*- FS
66	1		*REFRIGERANT LINE	Not Necessary	277.00 FS	*- FS
67	1		*BOLT	Not Necessary	3.00 FS	*- FS
68	1		*REFRIGERANT PIPE	Bent	585.00 FS	*468.00 FS
69	1		*REFRIGERANT PIPE BRACKET	Necessary	9.00 FS	*6.48 FS
70	1		*REFRIGERANT PIPE BRACKET	Necessary	21.00 FS	*16.32 FS
71	1		*RADIATOR	Not Necessary	699.00 FS	*- FS
72	1		*ADDITIONAL RADIATOR	Not Necessary	545.00 FS	*- FS
73	1		*FAN RING	Not Necessary	291.00 FS	*- FS
74	1		*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	2,483.00 FS	*- FS
75	1		*RADIATOR AIR GUIDE - LH	Not Necessary	32.00 FS	*- FS
76	2		*RADIATOR AIR GUIDE - LH / RH UPPER	Not Necessary	28.00 FS	*- FS
77	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
78	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
79	1		*COOLANT (6PCS)	Necessary	282.00 FS	*237.12 FS
80	1		*FRONT DOOR WINDOW SLOT SEAL - LH	Not Necessary	344.00 FS	*- FS
81	1		*WINDSCREEN WATER DEFLECTOR - LH	Not Necessary	75.00 FS	*- FS
82	1		*FRONT DOOR WINDOW TRIM STRIP - LH	Not Necessary	287.00 FS	*- FS
83	1		*INTAKE AIR DUCT	Not Necessary	25.00 FS	*- FS
84	1		*INTAKE AIR GUIDE	Not Necessary	61.00 FS	*- FS
85	1		*INTAKE HOSE	Not Necessary	110.00 FS	*- FS
86	1		*AIR FILTER	Not Necessary	418.00 FS	*- FS
87	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
88	1		*SUNDRIES	Necessary	500.00 FS	*23.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 35,500.00 19,920.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL LHS AND RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS AND RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR	New	560.00	560.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR, LHS FRONT FENDER TOP SUPPORT AND LHS UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,000.00	3,000.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER, LHS FRONT FENDER TOP SUPPORT, LHS UPPER A-PILLAR AND LHS FRONT DOOR	New	5,000.00	3,025.00
6	TO CARRY OUT PRE WHEEL ALIGNMENT	New	240.00	0.00
7	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE	New	280.00	280.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
9	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
Gross Labour Cost (\$\$)			14,694.00	9,379.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >