



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 3391U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	612.25	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	172.10	-
1	REAR FENDER RH	BENT	1,082.25	1,082.25
1	REAR DOOR RH	TO REPAIR SEE LABOUR	971.75	-
1	RR DOOR OUTER CTR MOULDING RH	TO REPAIR SEE LABOUR	174.45	-
	LESS 25% DISCOUNT		-753.20	-270.56
			2,259.60	811.69
	<u>NETT ITEMS</u>			
10	REAR BUMPER CLIPS @\$4.00 (SN)	NOT NECESSARY	40.00	-
	LESS 10% DISCOUNT		-4.00	-
			36.00	-
	<u>LABOUR</u>			
	ANTI-RUST.		100.00	100.00
	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR DOOR RH AND RR DOOR OUTER CTR MOULDING RH.		800.00	600.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	600.00
	TO CHECK WIRING.	NOT NECESSARY	30.00	-
	TO TRANSFER DOOR GLASS MECHANISM LH.	NOT NECESSARY	60.00	-
			1,990.00	1,300.00
	GRAND TOTAL		4,285.60	2,111.69
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,650.00

Report Ref No. CS/SMR22007203/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.