

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122007205/EQY3Q2**Date:** 13/09/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SKW6455E **Insured Vehicle No :** YP6394T

Date of Loss: 27/07/2022 Nature of Claim: TP Claim No: CDMCG22001501

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW6455E**

Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: K24W71012131

Reg. Date: 09/11/2015 (Man. Year: 2015) Chassis No: JHMRC1890FC205013

Colour: Purple Odometer: 143982 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R15 Rear Tyre Size: 205/55 R15

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,221.40	5,922.40	2,299.00	27.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,110.00	1,490.00	41.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,821.40	8,032.40	3,789.00	32.05
Approved Total (Overridden) (S\$)		6,450.00		
(S\$)	11,821.40	6,450.00	5,371.40	45.44
+ GST 7.00/7.00% (S\$)	827.50	451.50	376.00	45.44
Nett Amount (S\$)	12,648.90	6,901.50	5,747.40	45.44

INSPECTION

Date of Assignment: 28/07/2022

Date Inspected: 28/07/2022 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)
38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2022)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW6455E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,298.00 FL	*1,171.00 FL
2	1		*BOOT LID LOCK	Bent	204.00 FL	*204.00 FL
3	1		*BOOT LID WEATHERSTRIP	Crushed	126.00 FL	*126.00 FL
4	2		*BOOT LID LAMP LH/RH	Broken	824.00 FL	*824.00 FL
5	1		*BOOT LID LOGO BADGE	Missing	27.00 FL	*27.00 FL
6	1		*BOOT LID CENTER GARNISH WITH ODYSSEY	Cut	247.00 FL	*247.00 FL
7	1		*BOOT LID SIDE INNER TRIM BOARD LH	Missing	51.00 FL	*51.00 FL
8	1		*BOOT LID INNER TRIM BOARD	Cut	243.00 FL	*243.00 FL
9	1		*BOOT LID CENTER LOWER CHROME	Broken	195.00 FL	*195.00 FL
10	1		*BOOT LID LOCK BUZZER (END PANEL BUZZER)	Broken	85.00 FL	*85.00 FL
11	1		*END PANEL	Dented	492.00 FL	*492.00 FL
12	1		*END PANEL TOP GARNISH	Broken	121.00 FL	*121.00 FL
13	2		*TAIL LAMP LH/RH	Not Necessary	1,788.00 FL	*- FL
14	1		*REAR WINDSCREEN WIPER ARM ASSY	Cut	57.00 FL	*25.00 FL
15	1		*WIPER BADGE	Cut	48.00 FL	*48.00 FL
16	1		*REAR BUMPER	Dented	984.00 FL	*631.00 FL
17	2		*REAR BUMPER SIDE RETAINER LH/RH	Broken	40.00 FL	*40.00 FL
18	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
20	1		*REAR REVERSE SENSOR	Broken	200.00 FS	*200.00 FS
21	1		*END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
22	1		*V KOOL SOLAR FILM	Necessary	200.00 FS	*150.00 FS
23	2		*INNER TRIM BOARD LH/RH	Broken	1,700.00 FL	*1,370.00 FL
24	2		*BOOT LID DAMPER LH/RH	Bent	378.00 FL	*378.00 FL
25	1		*FLOOR PANEL SEALANT	Not Necessary	60.00 FS	*- FS
26	1		*SET CAR CAMERA	Missing	480.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,003.00	7,178.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,781.60	1,255.60
Total Parts (\$\$)	8,221.40	5,922.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	1,000.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEM & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	800.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	90.00	30.00
4	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	90.00	30.00
5	TO REMOVE AND REFIT REAR COMPARTMENT FITTINGS TRIMMINGS ,GARNISH AND ETC	New	100.00	50.00
6	TO REMOVE AND REPLACE REAR WINDSCREEN	New	120.00	120.00
7	TO REMOVE AND REPLACE INNER REAR REVERSE SENSOR	New	100.00	30.00
8	TO CARRIER VACUUM AND INTERIOR CLEANING	New	100.00	50.00
9	TO REPAIR AND SPRAY PAINTING ON END INNER PANEL (REFER MAIN LABOUR)	New	200.00	0.00
10	TO REPAIR AND SPRAY PAINTING ON END INNER PANEL (REFER MAIN LABOUR)	New	200.00	0.00
11	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED & REPAIRED (REFER MAIN LABOUR)	New	400.00	0.00
Gross Labour Cost (\$\$)			3,600.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >