

ASS. REC. BY:

REF:

AG21 2200 7217 / K943

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GB11 7256

Yr Regn:

09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen

Caddy C.C

1968

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

60937

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WV1 777 2K 24X163143

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Chamatai

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

25/7/22

D.O.I.

29/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

GIA & EN not ready

5/8

11Rm @ 1600

Cable

(Red. \$ 9217.50, 85%)

Date/Time, File Pass to?

1) 5/9/22

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) \$ + RS. \$

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

1600

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: VOLKSWAGEN CADDY

Engine/Chassis No.: WV1ZZZ2KZHX163143

Date of accident:


Damaged area: O/S

Date: 29/07/2022

Claim Type: TP

VRN: GBH7256S

Not Withheld
 1/1 Png & 1600k
 Return After Pamy
 3 days



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Tail lamp o/s	1	\$ 668.00	\$ 668.00	X
2	Rear bumper side retainer	2	\$ 75.00	\$ 150.00	X
3	Rear bumper <i>788.60</i>	1	\$ 978.00	\$ 978.00	✓
4	Sliding door o/s	1	\$ 1,589.00	\$ 1,589.00	X
5	Sliding door weatherstrip o/s	1	\$ 119.00	\$ 119.00	X
6	Sliding door outer moulding o/s	1	\$ 238.00	\$ 238.00	X
7	Rear fender lower o/s	1	\$ 776.00	\$ 776.00	X
8	Rear fender inner shield o/s	1	\$ 185.00	\$ 185.00	X
9	Rear wheel hub o/s	1	\$ 256.00	\$ 256.00	—
10	Rear wheel hub bearing o/s	1	\$ 149.00	\$ 149.00	—
11	Rear axle	1	\$ 2,557.00	\$ 2,557.00	X
Subtotal				\$ 7,665.00	
List discount				10.00%	
Total				\$ 6,898.50	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper clips	12	\$ 5.50	\$ 66.00	✓
2	Sliding door inner trim clips o/s	16	\$ 5.50	\$ 88.00	X
3	Rear fender inner shield clips o/s	10	\$ 5.50	\$ 55.00	X
4	Rear steel wheel o/s	1	\$ 350.00	\$ 350.00	X
5	Rear steel wheel cover o/s	1	\$ 180.00	\$ 180.00	✓ 9052
6	Rear tyre o/s	1	\$ 280.00	\$ 280.00	X
7	Sundries	1	\$ 50.00	\$ 50.00	X
Total				\$ 1,069.00	

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit o/s sliding door components for replacement, check and re-adjust close gap, alignment and water seepage.	0.5	\$ <i>na</i> 100.00
4	To rust proof all affected portions after repair.	0.5	\$ <i>na</i> 100.00
5	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
Total labour			\$ 2,850.00
Estimate Grand Total			\$ 10,817.50

4001

151

X

X

4001

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: