

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007218/VQY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00015622205
Claimant Vehicle No :	SGC6936L	Insured Vehicle No :	SKH7957X
Date of Loss:	24/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D205148/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC6936L	Engine No:	PY30421949
Make & Model:	MAZDA CX-5, 2.0 (A)	Chassis No:	JM6KE1032G0313542
Reg. Date:	19/05/2015 (Man. Year: 2015)	Odometer:	112100 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R19	Rear Tyre Size:	225/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,429.90	2,307.90	1,122.00	32.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,070.00	2,910.00	2,160.00	42.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,499.90	5,217.90	3,282.00	38.61
+ GST 7.00/7.00% (\$\$)	594.99	365.25	229.74	38.61
Nett Amount (\$\$)	9,094.89	5,583.15	3,511.74	38.61

INSPECTION

Date of Assignment:	28/07/2022		
Date Inspected:	01/08/2022	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	4.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2022)
Parts:	M1-SUV	MAZDA CX-5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC6936L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER KE	Cut	1,278.90 F	*1,278.90 F
2	2		*RETAINER S S ULTRASONIC CENTER	Necessary	20.40 F	*20.40 F
3	5		*PAD PROTECTOR	Necessary	39.00 F	*39.00 F
4	2		*RETAINER S ULTRASONIC SIDE	Not Necessary	31.00 F	*- F
5	2		*SENSOR ULTRASONIC SIDE	Not Necessary	361.80 F	*- F
6	2		*SENSOR ULTRASONIC CENTER	Not Necessary	405.20 F	*- F
7	1		*REINFORCEMENT REAR	Dented	520.00 F	*520.00 F
8	2		*STAY REAR BUMPER	Necessary	34.60 F	*34.60 F
9	1		*BRACKET CENTER REAR BUMPER	Necessary	5.40 F	*5.40 F
10	6		*GROMMET SCREW	Necessary	16.20 F	*16.20 F
11	2		*TAPE PROTECTOR	Necessary	15.20 F	*15.20 F
12	1		*REFLECTOR LH	Serviceable	106.30 F	*- F
13	1		*REFLECTOR RH	Serviceable	106.30 F	*- F
14	1		*COVER RH TOWING HOOK	Missing	2.70 F	*2.70 F
15	1		*COVER LH TOWING HOOK	Missing	2.70 F	*2.70 F
16	2		*FASTENER	Necessary	6.00 F	*6.00 F
17	1		*RETAINER RH REAR BUMPER	Necessary	34.10 F	*34.10 F
18	1		*RETAINER LH REAR BUMPER	Necessary	34.10 F	*34.10 F
19	1		*GASKET RH LAMP TRUNK LID	Necessary	45.90 F	*45.90 F
20	1		*GASKET LH LAMP TRUNK LID	Necessary	45.90 F	*45.90 F
21	1		*GASKET RH TAIL LAMP	Necessary	37.00 F	*37.00 F
22	1		*GASKET LH TAIL LAMP	Necessary	37.00 F	*37.00 F
23	1		*ORNAMENT CX-5	Necessary	47.60 F	*47.60 F
24	1		*ORNAMENT SKYACTIV	Necessary	75.20 F	*75.20 F
25	1		*MASCOT REAR	Serviceable	54.30 F	*- F
26	3		*CLIP	Serviceable	17.10 F	*- F
27	1		*SUNDRIES	Necessary	50.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,429.90** **2,307.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND REPAIR TAILGATE	New	1,500.00	660.00
2	TO RESPRAY REAR BUMPER AND TAILGATE	New	1,400.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	660.00	330.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	180.00
6	REPAIR LOWER SECTION OF THE TAILGATE	New	330.00	330.00
7	SPRAY TAILGATE	New	630.00	630.00
Gross Labour Cost (\$\$)			5,070.00	2,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >