

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007219/AVCE2**Date:** 21/11/2022REFERENCE

Insured/Claimant: ZAWIYAH BINTE MOHAMED ZAIN

Policy No: 1900236767-01

Date of Loss: 26/07/2022

Nature of Claim: OD

Claim No: 8845859196SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMQ1698L**

Make & Model: AUDI A6, 2.0 TFSI (A)

Engine No: DLH066959

Reg. Date: 31/10/2019 (Man. Year: 2019)

Chassis No: WAUZZZF2XLN013689

Colour: Blue

Odometer: 25242 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$180,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 18,501.00 | 7,937.36 | 10,563.64 | 57.10 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,752.00 | 3,022.00 | 3,730.00 | 55.24 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 25,253.00 | 10,959.36 | 14,293.64 | 56.60 |
| - Excess (S\$) | 800.00 | 800.00 | 0.00 | 0.00 |
| (S\$) | 24,453.00 | 10,159.36 | 14,293.64 | 58.45 |
| + GST 7.00/7.00% (S\$) | 1,711.71 | 711.16 | 1,000.55 | 58.45 |
| Nett Amount (S\$) | 26,164.71 | 10,870.52 | 15,294.19 | 58.45 |

INSPECTION

Date of Assignment: 29/07/2022

Date Inspected: 28/07/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Distorted | 3,012.00 FS | *2,409.60 FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Not Necessary | 658.00 FS | *- FS |
| 3 | 1 | | *FRONT RADIATOR GRILLE CLOSING ELEMENT | Not Necessary | 248.00 FS | *- FS |
| 4 | 1 | | *FRONT BUMPER SIDE REINFORCEMENT - RH | Not Necessary | 44.00 FS | *- FS |
| 5 | 1 | | *FRONT BUMPER LOWER GRILLE - CENTRE | Not Necessary | 125.00 FS | *- FS |
| 6 | 1 | | *FRONT BUMPER CLOSING ELEMENT - LOWER | Not Necessary | 171.00 FS | *- FS |
| 7 | 1 | | *FRONT BUMPER SPOILER | Not Necessary | 235.00 FS | *- FS |
| 8 | 1 | | *FRONT BUMPER AIR GRILLE - RH | Not Necessary | 485.00 FS | *- FS |
| 9 | 2 | | *FRONT BUMPER AIR GUIDE - RH | Not Necessary | 57.00 FS | *- FS |
| 10 | 1 | | *FRONT BUMPER GUIDE SECTION - RH | Not Necessary | 50.00 FS | *- FS |
| 11 | 1 | | *FRONT BUMPER BRACKET - RH | Not Necessary | 61.00 FS | *- FS |
| 12 | 1 | | *FRONT BUMPER TOP COVER | Not Necessary | 140.00 FS | *- FS |
| 13 | 1 | | *FRONT BUMPER REINFORCEMENT FOAM | Not Necessary | 252.00 FS | *- FS |
| 14 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 1,076.00 FS | *- FS |
| 15 | 1 | | *FRONT BUMPER SUPPORT | Not Necessary | 67.00 FS | *- FS |
| 16 | 1 | | *RIVET | Not Necessary | 6.00 FS | *- FS |
| 17 | 1 | | *CAUTION STICKER | Not Necessary | 16.00 FS | *- FS |
| 18 | 1 | | *FRONT FENDER - RH | Dented | 1,649.00 FS | *1,319.20 FS |
| 19 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Not Necessary | 44.00 FS | *- FS |
| 20 | 1 | | *FRONT FENDER BRACE - RH | Not Necessary | 137.00 FS | *- FS |
| 21 | 1 | | *FRONT FENDER BRACKET - UPPER | Not Necessary | 49.00 FS | *- FS |
| 22 | 1 | | *FRONT HEADLIGHT - RH | Cut | 9,172.00 FS | *3,895.20 FS |
| 23 | 1 | | *FRONT NO PLATE | Not Necessary | 60.00 FS | *- FS |
| 24 | 1 | | *SUNDRIES | Necessary | 300.00 FS | *4.32 FS |
| 25 | 1 | | *FRONT BUMPER ADAPTER RHS/LHS (Supplementary) | Damaged | 88.00 FS | *70.24 FS |
| 26 | 1 | | *RHS FRONT WHEEL HOUSING LINER (Supplementary) | Torn | 299.00 FS | *238.80 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **18,501.00** **7,937.36**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New | 480.00 | 480.00 |
| 2 | TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE | New | 400.00 | 250.00 |
| 3 | TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR | New | 280.00 | 0.00 |
| 4 | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 2,400.00 | 1,000.00 |
| 5 | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR | New | 3,000.00 | 1,100.00 |
| 6 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 6,752.00 | 3,022.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >