



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 6519J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR WINDSCREEN	NOT NECESSARY	1,288.10	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	145.40	-
1	TAILGATE	TO REPAIR SEE LABOUR	1,742.00	-
1	TAILGATE OUTER HANDLE	NOT NECESSARY	299.40	-
2	TAILGATE REFLECTORS @\$182.40	NOT NECESSARY	364.80	-
1	TAILGATE INNER LOCK	NOT NECESSARY	616.80	-
1	TAILGATE WEATHERSTRIP	TWISTED	386.20	386.20
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	567.30	-
1	REAR BUMPER	DISTORTED	665.90	545.10
2	REAR BUMPER DAMPERS @\$85.00	N/S BENT (1PIECE ONLY)	170.00	85.00
2	REAR BUMPER SIDE RETAINERS @\$65.00	N/S BENT (1PIECE ONLY)	130.00	65.00
2	REAR BUMPER REFLECTORS @\$60.00	N/S CRACKED (1PIECE ONLY)	120.00	60.00
1	REAR END PANEL OUTER	DENTED / BENT	842.00	615.10
1	REAR END PANEL LOWER	NO SUCH PARTS	389.20	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	381.80	-
2	TAILLAMPS @\$395.00	NOT NECESSARY	790.00	-
1	REAR FENDER INNER TRIM BOARD O/S	NOT NECESSARY	645.20	-
1	REAR FENDER UNDER SHIELD O/S	NOT NECESSARY	121.50	-
	LESS 25% DISCOUNT		-2,416.40	-439.10
			7,249.20	1,317.30
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	50.00	-
1	SET TAILGATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			480.00	250.00

Report Ref No. CS/AGI22007230/Uvy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REPLACED REAR REVERSE SENSOR.		80.00	50.00
	TO REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIX TAILGATE MECHANISM.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO REMOVE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIX FUEL TANK.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIX REAR REVERSE CAMERA.	NOT NECESSARY	100.00	-
	TO SPRAY ANTI-RUST PROOFING.		120.00	30.00
	TO DIAGNOSIS & REPROGRAMME SYSTEM.	NOT NECESSARY	180.00	-
	LABOUR FOR PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILGATE.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	800.00
			4,100.00	1,580.00
<b>GRAND TOTAL</b>			<b>11,829.20</b>	<b>3,147.30</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,500.00</b>
---	--	--	-----------------

Report Ref No. CS/AGI22007230/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.