

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007231/KQY3Q2**Date:** 28/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00163542100

**Claimant Vehicle No :** SLL8916A **Insured Vehicle No :** SJD4795Z

Date of Loss: 27/07/2022 Nature of Claim: TP Claim No: SNM22D205286/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLL8916A**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZRY324299

Reg. Date: 15/03/2017 (Man. Year: 2016) Chassis No: MR053REH104557169

Colour: Metallic Grey Odometer: 92778 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 5,209.00          | 3,238.40          | 1,970.60          | 37.83         |
| Miscellaneous Items                      | 235.00            | 235.00            | 0.00              | 0.00          |
| Labour                                   | 3,890.00          | 3,390.00          | 500.00            | 12.85         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>9,334.00</b>   | <b>6,863.40</b>   | <b>2,470.60</b>   | <b>26.47</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>6,400.00</b>   |                   |               |
| <b>(S\$)</b>                             | 9,334.00          | 6,400.00          | 2,934.00          | 31.43         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 653.38            | 448.00            | 205.38            | 31.43         |
| <b>Nett Amount (S\$)</b>                 | <b>9,987.38</b>   | <b>6,848.00</b>   | <b>3,139.38</b>   | <b>31.43</b>  |

**INSPECTION**

Date of Assignment: 16/08/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 29/07/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

Estimated Period of Repair: 10.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                                                              |                                                                                                                                                                              |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 28 Dec 2022)                                                                                                                                |
| <b>Parts:</b> 143                                            | TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)                                                                                                           |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for SLL8916A) |                                                                                                                                                                              |
| <b>Validity:</b>                                             | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                         | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

### Recommended Parts

| No. | Qty | Part No. Particulars                             | Condition          | Repairer's | Amount     |
|-----|-----|--------------------------------------------------|--------------------|------------|------------|
| 1   | 1   | *1 PC REAR BUMPER                                | Bent               | 200.00 F   | *200.00 FL |
| 2   | 1   | *1 PC REAR BUMPER REINFORCEMENT                  | Bent               | 115.00 F   | *115.00 FL |
| 3   | 1   | *1 PC REAR BUMPER REINFORCEMNT INNER RETAINER LH | Distorted          | 40.00 F    | *40.00 FL  |
| 4   | 1   | *1 PC REAR BUMPER REINFORCEMNT INNER RETAINER RH | Distorted          | 40.00 F    | *40.00 FL  |
| 5   | 1   | *1 PC REAR BUMPER SIDE RETAINER LH               | Distorted          | 35.00 F    | *35.00 FL  |
| 6   | 1   | *1 PC REAR BUMPER SIDE RETAINER RH               | Distorted          | 35.00 F    | *35.00 FL  |
| 7   | 1   | *6 PCS REAR BUMPER CLIPS @2/PC                   | Necessary          | 12.00 F    | *12.00 FL  |
| 8   | 1   | *1 PC REAR BUMPER LH BRACKET                     | Bent               | 38.00 F    | *38.00 FL  |
| 9   | 1   | *1 PC REAR BUMPER RH BRACKET                     | Bent               | 38.00 F    | *38.00 FL  |
| 10  | 1   | *1 PC REAR SMART KEY SENSOR                      | Cracked            | 48.00 F    | *48.00 FL  |
| 11  | 1   | *1 PC BOOTLID                                    | Bent               | 320.00 F   | *320.00 FL |
| 12  | 1   | *1 PC BOOTLID INSULATOR                          | Serviceable        | 190.00 F   | *- FL      |
| 13  | 1   | *6 PCS BOOTLID INSULATOR CLIPS @2/PC             | Necessary          | 12.00 F    | *12.00 FL  |
| 14  | 1   | *1 PC BOOTLID LOGO                               | Necessary          | 28.00 F    | *28.00 FL  |
| 15  | 1   | *1 PC BOOTLID EMBLEM (COROLLA)                   | Necessary          | 35.00 F    | *35.00 FL  |
| 16  | 1   | *1 PC BOOTLID EMBLEM (ALTIS)                     | Necessary          | 35.00 F    | *35.00 FL  |
| 17  | 1   | *1 PC LH TAILLAMP                                | Serviceable        | 148.00 F   | *- FL      |
| 18  | 1   | *1 PC RH TAILLAMP                                | Mtg Cracked        | 148.00 F   | *148.00 FL |
| 19  | 1   | *1 PC REA END PANEL                              | Bent               | 230.00 F   | *230.00 FL |
| 20  | 1   | *1 PC REA END PANEL INNER TRIM                   | Mtg Distorted      | 95.00 F    | *95.00 FL  |
| 21  | 1   | *3 PCS REAR END PANEL INNER TRIM CLIPS @2/PC     | Necessary          | 6.00 F     | *6.00 FL   |
| 22  | 1   | *1 PC BOOTLID UPPER LOCK                         | Dented             | 150.00 F   | *150.00 FL |
| 23  | 1   | *1 PC BOOTLID WEATHER STRIP                      | Distorted / Dented | 60.00 F    | *60.00 FL  |
| 24  | 1   | *1 PC REAR FLOOR TOP COVER BOARD                 | Serviceable        | 170.00 F   | *- FL      |
| 25  | 1   | *1 PC REAR SPARE TYRE COMPARTMENT                | Repair             | 380.00 F   | *- FL      |
| 26  | 1   | *1 PC FRT BUMPER                                 | Cracked            | 210.00 F   | *210.00 FL |
| 27  | 1   | *1 PC FRT BUMPER ABSORBER FOAM                   | Serviceable        | 55.00 F    | *- FL      |
| 28  | 1   | *1 PC FRT BUMPER REINFORCEMENT                   | Repair             | 160.00 F   | *- FL      |
| 29  | 1   | *1 PC FRT GRILLE                                 | Cracked            | 150.00 F   | *150.00 FL |
| 30  | 1   | *1 PC FRT BRACE PANEL                            | Bent               | 58.00 F    | *58.00 FL  |
| 31  | 1   | *1 PC FRT TOP COVER                              | No such part       | 58.00 F    | *- FL      |
| 32  | 1   | *1 PC HEADLAMP LH                                | Mtg Cracked        | 600.00 F   | *600.00 FL |
| 33  | 1   | *1 PC HEADLAMP RH                                | Mtg Cracked        | 600.00 F   | *600.00 FL |
| 34  | 1   | *1 PC FRT SUPPORT PANEL                          | Buckled            | 290.00 F   | *290.00 FL |

#### Supplementary #1

|    |   |                        |           |          |            |
|----|---|------------------------|-----------|----------|------------|
| 35 | 1 | *1 PC AIRCON CONDENSOR | Punctured | 420.00 F | *420.00 FL |
|----|---|------------------------|-----------|----------|------------|

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)**    **5,209.00**    **4,048.00**  
**- List Item Discount on L Items 0.00/20.00% (\$\$)**    0.00    809.60

**Total Parts (\$\$)**    **5,209.00**    **3,238.40**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

| No                         | Qty | Particulars           | Repairer's    | Amount        |
|----------------------------|-----|-----------------------|---------------|---------------|
| <b>Miscellaneous Items</b> |     |                       |               |               |
| 1                          | 1   | 1 PC FRT NUMBER PLATE | 35.00         | 35.00         |
| 2                          | 1   | 1 SET REVERSE SENSOR  | 200.00        | 200.00        |
| <b>Sub Total (\$\$)</b>    |     |                       | <b>235.00</b> | <b>235.00</b> |

## Recommended Labour

| No                              | Particulars                                                                                                                                                            | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                                        |          |                 |                 |
| 1                               | REMOVE & REFIX REAR WINDSCREEN GLASS                                                                                                                                   | New      | 100.00          | 0.00            |
| 2                               | REMOVE & REFIX REAR BUMPER,REAR BOOT & ATTACHMENT,TAILLAMPS,LOCK ASSY,TO CUT,WELD & RENEW REAR PANEL,REAR COMPARTMENT,KNOCK & REPAIR REAR FENDERS AND REALIGN THE SAME | New      | 1,100.00        | 950.00          |
| 3                               | REMOVE & REFIX SEAT,REAR GARNISH,ETC                                                                                                                                   | New      | 50.00           | 50.00           |
| 4                               | PUTTY & RESPRAY ON REAR BUMPER,REINFORCEMENT,BOOT,HINGES,REAR PANEL,REAR COMPARTMENT,REAR FENDER                                                                       | New      | 1,100.00        | 1,000.00        |
| 5                               | REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,GRILLE,RADIATOR & MOTOR,TO KNOCK & REPAIR FRT SUPPORT PANEL AND REALIGN THE SAME                                       | New      | 600.00          | 550.00          |
| 6                               | PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT,SUPPORT PANEL,BONNET                                                                                                       | New      | 700.00          | 600.00          |
| 7                               | REMOVE & REFIX AIRCON,CHECK,VACUUM & REFILL GAS                                                                                                                        | New      | 100.00          | 100.00          |
| 8                               | REMOVE & REFIX REVERSE CAMERA,SENSOR,SMART KEY SENSOR AND RESET SYSTEM                                                                                                 | New      | 50.00           | 50.00           |
| 9                               | RUSTPROOFING                                                                                                                                                           | New      | 90.00           | 90.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                                        |          | <b>3,890.00</b> | <b>3,390.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >