



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDY 9339K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	543.90	543.90
1	FRONT BUMPER SIDE HOLDER RH (CONSISTENT)	DAMAGED	65.40	65.40
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	395.80	-
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	138.40	138.40
1	FRONT BUMPER FOG LAMP RH (CONSISTENT)	NOT NECESSARY	337.20	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	CRACKED	245.90	245.90
1	FRONT BUMPER SENSOR RH (CONSISTENT)	DAMAGED	245.00	245.00
1	FRONT BUMPER AIR VENT RH (CONSISTENT)	DEFORMED	54.90	54.90
1	HEADLAMP RH (CONSISTENT)	CRACKED	1,885.40	1,885.40
1	FRONT RH FENDER (CONSISTENT)	DENTED	797.30	797.30
1	FRONT RH FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	190.70	-
1	WIPER WASHER TANK (CONSISTENT)	DEFORMED	145.10	145.10
1	WIPER WASHER TANK MOTOR (CONSISTENT)	NOT NECESSARY	150.40	-
	LESS 25% DISCOUNT		-	-1,030.33
			5,195.40	3,090.97
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT RH FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT RH WHEEL RIM (SN) (CONSISTENT)	NOT NECESSARY	850.00	-
1	FRONT RH TYRE (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
			1,210.00	30.00
<u>LABOUR</u>				
	PANEL BEATING.		800.00	500.00
	SPRAY PAINTING.		800.00	600.00
	WIRING.		100.00	50.00
	TO SPRAY TUFF COAT.		150.00	40.00
	TO REMOVE FRONT BUMPER SENSORS.		100.00	50.00

Report Ref No. CS/ASM22007238/Avy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			2,100.00	1,240.00
GRAND TOTAL			8,505.40	4,360.97
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CS/ASM22007238/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.