

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007242/ANY3Q2**Date:** 12/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00003302200
Claimant Vehicle No :	SCE85T	Insured Vehicle No :	GBJ992K
Date of Loss:	28/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D205293/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCE85T	Engine No:	L15B3518858
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11018843
Reg. Date:	23/06/2015 (Man. Year: 2015)	Odometer:	117176 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,250.08	4,077.20	6,172.88	60.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,930.00	1,310.00	3,620.00	73.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,180.08	5,387.20	9,792.88	64.51
Approved Total (Overridden) (\$\$)		4,300.00		
Nett Amount (\$\$)	15,180.08	4,300.00	10,880.08	71.67

INSPECTION

Date of Assignment:	01/08/2022	
Date Inspected:	29/07/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCE85T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,085.00 FL	*745.00 FL
2	1		*FRONT BUMPER LOWER LIP	Not Necessary	381.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	46.00 FL	*23.00 FL
4	1		*HEADLAMP LH (LED)	Cracked	1,859.40 FL	*1,859.40 FL
5	1		*HEADLAMP LOWER BRACKET	Not Necessary	59.00 FL	*- FL
6	1		*FRONT SIDE MIRROR LH	Damaged	841.60 FL	*841.60 FL
7	1		*FRONT DOOR LH	Repair	950.00 FL	*- FL
8	1		*FRONT DOOR OUTER STRIP LH	Not Necessary	87.00 FL	*- FL
9	1		*FRONT DOOR BLACK STICKER LH	Not Necessary	95.00 FL	*- FL
10	1		*FRONT FENDER LH	Dented	748.80 FL	*587.00 FL
11	1		*FRONT FENDER INNER GARNISH LH	Not Necessary	85.00 FL	*- FL
12	1		*FRONT FENDER ARCD GARNISH LH	Cut	195.00 FL	*195.00 FL
13	1		*FRONT FENDER INNER COWLING LH	Deformed	170.50 FL	*170.50 FL
14	1		*FRONT ABS SENSOR	Not Necessary	180.00 FL	*- FL
15	1		*FRONT SHOCK ABSORBER LH	Not Necessary	586.50 FL	*- FL
16	1		*FRONT LOWER ARM LH	Not Necessary	474.70 FL	*- FL
17	1		*FRONT KNUCKLE ARM LH	Not Necessary	461.70 FL	*- FL
18	1		*FRONT KNUCKLE ARM INNER BEARING LH	Not Necessary	262.00 FL	*- FL
19	1		*FRONT WHEEL HUP LH	Not Necessary	379.40 FL	*- FL
20	1		*FRONT LINKAGE LH	Not Necessary	65.00 FL	*- FL
21	1		*FRONT STEERING RACK & PINION	Not Necessary	1,750.00 FL	*- FL
22	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
23	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
24	1		*SET FRONT WIPER PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
25	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
26	1		*SET FRONT FENDER INNER COWLING CLIP RH	Necessary	50.00 FS	*30.00 FS
27	1		*SET FRONT FENDER ARCED GARNISH CLIP LH	Necessary	50.00 FS	*30.00 FS
28	1		*FRONT WHEEL TYRE LH	Not Necessary	450.00 FS	*- FS
29	1		*FRONT WHEEL RIM LH	Cut	850.00 FS	*450.00 FS
30	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,402.60	4,961.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,152.52	884.30
Total Parts (\$\$)	10,250.08	4,077.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	700.00
3	WIRING CHECK	New	120.00	30.00
4	REFOCUS HEADLAMP BEAM	New	80.00	0.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX FRONT DOOR MECHANISM	New	80.00	0.00
7	REMOVE AND REFIX FRONT DOOR WINDOW GLASS	New	50.00	0.00
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
9	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	350.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	80.00
11	RESET ABS LIGHT	New	350.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,930.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >