



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

PRE-REPAIR INSPECTION REPORT

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS3/AGI22007243/Ecy3m4

Date: 21/12/2022

Code: AGI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMH 3920D	Veh. Inspected	FBP 6703H
Policy No.	P10491749R01	Coverage (\$)	0.00
Claim No.	C10016580/JL	Excess (\$)	0.00
Assign From	SALIZAWATI HAIZAR	Assign Date	29/07/2022

2. Vehicle Particulars & Condition


Make & Model	YAMAHA AEROX	c.c	155
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3SG4610KJ214298	Colour	GREY
Odometer	24822 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/80 R14	MAXXIS	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/80 R14	MAXXIS	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.



5. General Information

Accident Date	25/07/2022	Inspect Date / Time	03/08/2022 (12:17 PM)
Survey held at	DYNASTY MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-24 MIDVIEW BUILDING SINGAPORE 659578		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

5b. Estimate Days of Repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

ESTIMATED NORMAL PERIOD FOR REPAIR:

3 Working Days

Report Ref No. CS3/AGI22007243/Ecy3m4

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.