

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB22007244/RVY3M4**Date:** 27/09/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKA6250U **Insured Vehicle No :** SLM7580K

Date of Loss: 17/07/2022 Nature of Claim: TP Claim No: MFL2022D0003710

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA6250U**

Make & Model: TOYOTA YARIS E AUTO, 1.5 (A) Engine No: 1NZY271906

Reg. Date: 18/03/2011 (Man. Year: 2011) Chassis No: MR054HY9104067688

Colour: Grey Odometer: 88657 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,547.12	3,365.10	6,182.02	64.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,750.00	1,220.00	41.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,517.12	5,115.10	7,402.02	59.14
Approved Total (Overridden) (\$\$)		4,100.00		
Nett Amount (\$\$)	12,517.12	4,100.00	8,417.12	67.24

INSPECTION

Date of Assignment: 29/07/2022

Date Inspected: 01/08/2022 Inspected At:

Hing Lee Motor Car Repair & Welder Works -
Woodlands (HQ)
Blk 7 Woodlands Road Unit 397-D Yew Tee
Industrial Estate
Singapore 677996

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2022)
Parts:	144	TOYOTA YARIS E AUTO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA6250U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Bent	958.70 F	*820.00 FL
2	1		*REAR TAIL GATE W/STRIP	Necessary	371.75 F	*219.10 FL
3	1		*REAR TAIL GATE LOCK	Jammed	262.90 F	*240.40 FL
4	1		*REAR TAIL GATE LOGO	Necessary	121.10 F	*54.10 FL
5	1		*REAR TAIL GATE E EMBLEM	Necessary	131.41 F	*48.00 FL
6	1		*REAR TAIL GATE YARIS EMBLEM	Necessary	151.35 F	*60.00 FL
7	1		*REAR END PANEL	Bent	654.10 F	*575.00 FL
8	1		*REAR FLOOR PANEL	Serviceable	900.45 F	*- FL
9	1		*REAR END PANEL GARNISH	Deformed	371.45 F	*210.00 FL
10	1		*REAR TAIL GATE HANDLE	Serviceable	198.25 F	*- FL
11	1		*REAR TAIL GATE TRIM BOARD	Cracked	878.15 F	*450.20 FL
12	1		*REAR L x R TAIL LAMP ASSY	N/s Cracked	799.60 F	*283.20 FL
13	1		*REAR WIPER MOTOR ASSY	Serviceable	523.72 F	*- FL
14	1		*REAR BUMPER	Deformed	488.20 F	*398.00 FL
15	1		*REAR BUMPER BEAM	Not Necessary	351.75 F	*- FL
16	2		*REAR BUMPER BRACKET R x L	Bent	316.30 F	*224.00 FL
17	2		*REAR BUMPER RETAINER	Necessary	111.80 F	*86.40 FL
18	1		*REAR LH TAIL LAMP SUPPORT	Not Necessary	174.44 F	*- FL
19	1		*SET REAR 2 NO PLATE LAMP	Cracked	250.60 F	*140.00 FL
20	1		*REAR EXHAUST	Not Necessary	899.10 F	*- FL
21	1		*SET REAR GLASS MOULDING	Necessary	182.00 F	*182.00 FN
22	1		*REAR GLASS SEALANT	Necessary	50.00 FS	*30.00 FS
23	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
24	1		*REAR BUMPER SENSOR	Not Working	220.00 FS	*220.00 FS
25	1		*REAR NO PLATE ASSY	Cut	50.00 FS	*35.00 FS
26	1		*REAR BOOT INTERIOR TRIM BOARD CLIP	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	9,547.12	4,335.40
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	952.10
- Nett Item Discount on N Items 0.00/10.00% (\$)	0.00	18.20
Total Parts (\$)	9,547.12	3,365.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REAR BOOT INTERIOR REMOVE & REFIT	New	120.00	60.00
2	REAR BUMPER SENSOR REMOVE & REFIT	New	80.00	40.00
3	REAR GLASS REMOVE & REFIT	New	150.00	120.00
4	REAR END PANEL SEALANT	New	80.00	40.00
5	REAR EXHAUST REMOVE & REFIT	New	100.00	0.00
6	ANTI RUST	New	80.00	60.00
7	WIRING FEE	New	60.00	30.00
8	RESPRAY PAINTING	New	1,000.00	700.00
9	TO REPAIR REAR ACC DAMAGE PORTION	New	1,300.00	700.00
Gross Labour Cost (S\$)			2,970.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >