

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007245/KVY3Q2**Date:** 10/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00001582200

**Claimant Vehicle No :** SMN7560B **Insured Vehicle No :** CB8592J

Date of Loss: 28/07/2022 Nature of Claim: TP Claim No: SNM22D205289/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMN7560B**

Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 2NR8924823

Reg. Date: 27/08/2019 (Man. Year: 2019) Chassis No: NSP1707200866

Colour: Metallic Blue Odometer: 86568 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Habilead 4 mm Rear Left Side: Habilead 4 mm

Front Right Side: Habilead 4 mm Rear Right Side: Habilead 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,233.07	3,644.50	3,588.57	49.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	1,660.00	1,630.00	49.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>10,523.07</b>	<b>5,304.50</b>	<b>5,218.57</b>	<b>49.59</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	736.61	371.32	365.29	49.59
<b>Nett Amount (\$\$)</b>	<b>11,259.68</b>	<b>5,675.82</b>	<b>5,583.86</b>	<b>49.59</b>

**INSPECTION**

Date of Assignment: 04/08/2022

Date Inspected: 01/08/2022 Inspected At: MBM Wheelpower Pte Ltd (Sin Ming)  
176 Sin Ming Drive #01-15, Sin Ming AutoCare  
Singapore 575721

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Nov 2022)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMN7560B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Mldg Necessary Only	1,279.50 FL	*120.00 FL
2	1		*TAIL GATE	Bent	1,445.70 FL	*1,245.10 FL
3	1		*TAIL GATE WEATHERSTRIP	Distorted / Dented	372.50 FL	*372.50 FL
4	1		*TAIL GATE HINGE LH	Repair	75.00 FL	*- FL
5	1		*TAIL GATE HINGE RH	Repair	75.00 FL	*- FL
6	1		*TAIL GATE ABSORBER LH	Serviceable	262.00 FL	*- FL
7	1		*TAIL GATE ABSORBER RH	Serviceable	262.00 FL	*- FL
8	1		*TAIL GATE LOCK	Jammed	480.00 FL	*372.90 FL
9	1		*TAIL GATE STRIKER	Repair	45.00 FL	*- FL
10	1		*TAIL GATE LAMP LH	Cracked	395.70 FL	*385.10 FL
11	1		*TAIL GATE LAMP RH	Cut	395.70 FL	*385.10 FL
12	1		*TAIL LAMP LH	Serviceable	497.50 FL	*- FL
13	1		*TAIL LAMP RH	Broken	497.50 FL	*430.20 FL
14	1		*REAR BUMPER	Repair	850.50 FL	*- FL
15	1		*REAR BUMPER RH SIDE BRACKET	Serviceable	100.40 FL	*- FL
16	1		*REAR BUMPER LH SIDE BRACKET	Serviceable	100.40 FL	*- FL
17	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	89.00 FL	*- FL
18	1		*REAR BUMPER LH SIDE RETAINER	Serviceable	89.00 FL	*- FL
19	1		*REAR BUMPER EXTENSION CENTER	Dented / Cut	285.00 FL	*255.00 FL
20	1		*REAR BUMPER EXTENSION RH	Serviceable	196.00 FL	*- FL
21	1		*REAR BUMPER EXTENSION LH	Serviceable	196.00 FL	*- FL
22	10		*BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
23	1		*END PANEL	Bent	488.70 FL	*433.80 FL
24	1		*END PANEL TOP GARNISH	Dented	175.00 FL	*175.00 FL
25	1		*REAR RH FENDER OUTER MOULDING	Mtg Cracked	355.50 FL	*322.90 FL
26	1		*TAIL GATE OUTER MOULDING	Mtg Cracked	256.50 FL	*229.40 FL
27	1		*REAR WIPER COVER	Cracked	39.00 FL	*39.00 FL
28	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
29	1		*REAR NUMBER PLATE & HOLDER	Serviceable	50.00 FS	*- FS
30	1		*BODY SEALANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,574.10</b>	<b>4,836.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,341.03	1,191.50
<b>Total Parts (\$\$)</b>	<b>7,233.07</b>	<b>3,644.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	600.00
2	TO RESET ENGINE WARNING LIGHT (ABS,SRS ,ECU MEMORY & ETC)	New	300.00	0.00
3	TO APPLY ANTI RUST COATING	New	150.00	30.00
4	TO REMOVE & REPLACE REAR WINDSCREEN	New	150.00	120.00
5	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	60.00
6	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	50.00
7	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
8	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	780.00
<b>Gross Labour Cost (\$)</b>			<b>3,290.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >