

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22002533/GCY3E2-1

Date: 18/08/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0001545_01

Claimant Vehicle No : SFB9892B **Insured Vehicle No :** SMV121P

Date of Loss: 17/03/2022 Nature of Claim: TP Claim No: MPC2022D0001445

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFB9892B**
Make & Model: MERCEDES-BENZ E200, 2.0 AVG (A) Engine No: 27492031251474
Reg. Date: 15/01/2018 (Man. Year: 2017) Chassis No: WDD2130422A344760
Colour: Grey Odometer: 92811 km
Engine Capacity: 1991 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,889.10	6,967.64	3,921.46	36.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,290.00	1,510.00	53.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,689.10	8,257.64	5,431.46	39.68
Approved Total (Overridden) (S\$)		6,600.00		
Nett Amount (S\$)	13,689.10	6,600.00	7,089.10	51.79

INSPECTION

Date of Assignment: 29/07/2022

Date Inspected: 22/03/2022 Inspected At:

Estimated Period of Repair: 5.0 days

A T Performance (SIN MING)
160 SIN MING DRIVE, #07-18/19 SIN MING
AUTOCITY
Singapore 575722

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2022)
Parts:	143	MERCEDES-BENZ E200 2.0 AVG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFB9892B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,421.67 F	*2,240.00 FL
2	1		*BOOT LID LOGO	Necessary	54.00 F	*54.00 FL
3	1		*BOOT LID BADGE - E200	Necessary	93.61 F	*93.61 FL
4	1		*BOOT LID BADGE - 9G - TRONIC	Necessary	97.22 F	*97.22 FL
5	1		*BOOT LID LOCK	Serviceable	383.41 F	*- FL
6	1		*BOOT LID OUTER CHROME STRIP	Grazed / Cut	253.64 F	*156.70 FL
7	1		*BOOT LID RUBBER SEAL	Cut / Damaged	239.45 F	*239.45 FL
8	1		*TAIL LAMP	Cracked / Split	852.40 F	*780.00 FL
9	1		*TAIL LAMP LOWER BRACKET	Cracked	45.11 F	*45.11 FL
10	1		*REAR BUMPER	Cut / Damaged	2,011.82 F	*1,956.00 FL
11	1		*REAR BUMPER SIDE BRACKET	Serviceable	68.70 F	*- FL
12	1		*REAR BUMPER CENTRE SUPPORT	Cracked	131.66 F	*131.66 FL
13	1		*REAR BUMPER LOWER TRIM	Serviceable	372.60 F	*- FL
14	1		*REAR BUMPER CHROME STRIP	Cracked	323.31 F	*323.31 FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	841.11 F	*725.00 FL
16	2		*REAR BUMPER SENSOR	Damaged	372.00 F	*372.00 FL
17	6		*REAR BUMPER SENSOR HOLDER	Necessary	25.32 F	*25.32 FL
18	1		*REAR BUMPER REFLECTOR	Cracked	38.62 F	*38.62 FL
19	1		*REAR BUMPER EXHAUST TIP	Dented	422.52 F	*280.00 FL
20	1		*REAR END PANEL	Repair	1,604.88 F	*- FL
21	1		*REAR END PANEL GARNISH	Cracked	166.05 F	*166.05 FL
22	1		*REAR PANEL SEALANT	Repair	50.00 FS	*- FS
23	1		*C & C LABEL	Necessary	20.00 FS	*16.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,889.10	7,740.05
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	772.41
Total Parts (S\$)	10,889.10	6,967.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS	New	1,250.00	600.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	1,000.00	600.00
3	TO REMOVE AND REFIT REAR INTERIOR FITTINGS / ATTACHMENTS TO FACILITATE REPAIR	New	180.00	60.00
4	TO CHECK WIRING SYSTEM FOR PROPER FUNCTIONS	New	120.00	30.00
5	TO CARRY OUT DIAGNOSTIC TEST AND RESET SETTINGS WHERE NECESSARY	New	250.00	0.00
Gross Labour Cost (\$\$)			2,800.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >