

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007252/UPA3Q2**Date:** 04/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220019336
Claimant Vehicle No :	SKU2328B	Insured Vehicle No :	SGY59S
Date of Loss:	28/07/2022	Nature of Claim:	TP
		Claim No:	1047396871SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2328B		
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (R17) (A)	Engine No:	27492030381640
Reg. Date:	18/06/2015 (Man. Year: 2015)	Chassis No:	WDD2120362B151940
Colour:	Black	Odometer:	112037 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,484.50	1,403.50	81.00	5.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	685.00	150.00	535.00	78.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,169.50	1,553.50	616.00	28.39
+ GST 7.00/7.00% (\$\$)	151.87	108.75	43.12	28.39
Nett Amount (\$\$)	2,321.37	1,662.25	659.12	28.39
+ Car Rental (1.0 x S\$100.00/day) (\$\$)		100.00		
Nett Liability (\$\$)		1,762.25		

INSPECTION

Date of Assignment:	25/08/2022		
Date Inspected:	25/08/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	1.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT GRILLE WITH CHROME GARNISH	Cracked	1,515.00 FN	*1,515.00 FN
2	1		*FRT GRILLE MERCEDES BADGE	Not Necessary	90.00 FN	*- FN
3	1		*FRONT LICENCE PLATE	Bent	40.00 FS	*40.00 FS
					Sub Total (S\$)	1,645.00 1,555.00
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	160.50 151.50
					Total Parts (S\$)	1,484.50 1,403.50

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT	New	350.00	0.00
2	LABOUR CHARGE	New	300.00	150.00
3	WIRING	New	35.00	0.00
Gross Labour Cost (\$)			685.00	150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >